## NEW MEXICO OIL CONSERVATION COMMISSION Santa Fe, New Mexico

## MISCELLANEOUS REPORTS ON WELLS

Submit this report in TRIPLICATE to the District Office, Oil Conservation Commission, within 10 days after the work specified is completed. It should be signed and filed as a report on Beginning Drilling Operations, Results of test of casing shut-off, result of plugging of well, result of well repair, and other important operations, even though the work was witnessed by an agent of the Commission. See additional instructions in the Rules and Regulations of the Commission.

instructions in the Rules and Regulations of	the Commission.		by an agent of the Commission.	See additiona
	Indicate Nature of Re	port by Checking Bel	ow	
REPORT ON BEGINNING DRILLING OPERATIONS	REPORT ON RESU		REPORT ON REPAIRING WELL	
REPORT ON RESULT OF PLUGGING WELL	REPORT ON RECO	OMPLETION	REPORT ON (Other)	
	Anr	<b>11</b> 22 <b>,</b> 19 <b>5</b> 5	Roswell. New	Mexico
Following is a report on the work done				
(Company or Operator	ley	Signal-S	tate (Lease)	
Roach & Shepard (Contractor)	•	, Well No 1	in the FEA X NE 1/4 o	f Sec. 16
r.185, r.28 <u>E</u> , nmpm.,	irtosia -	Pool,	Eddy	County
The Dates of this work were as folows:	April 18th,	1955		
Notice of intention to do the work (was) (was	as not) submitted on Form	n C-102 on	ch 15 (Cross out incorrect words)	
and approval of the proposed plan (was) (was	as not) obtained.			
DETAILED	ACCOUNT OF WORK	DONE AND RESUI	TS OBTAINED	
565 feet of 8 5, casing was test	'8 casing was ed resulting i	cemented wit n a shut off	th 75 sacks of ceme of surface water.	ent,
Witnessed by(Name)		(Company)	(Title)	
Approved: OIL CONSERVATION COMMISSION		I hereby certify that to the best of my kr	t the information given above is tru	e and complete
M. G. Stanso.	u	Name	V. M. Minley	<u> </u>
	-	Position OWITE1	. H. McKinley	
(Title)	(Date)	Address 908	W 5th St. Roswell	N. M.

## OIL CONSERVATION COMMISSION

205 CARPER BUILDING

ARTESIA, NEW MEXICO

March 21, 1955

Mr. W. H. McKinley 908 West 5th Street Roswell, New Mexico

Dear Bill:

With regard to your surface casing as outlined on your Form C-101, Notice of Intention to Drill, for your Signal-State No. 1 in Section 16-183-28E, Artesia Pool, it is my opinion that we should use 75 sacks of cement on the 500 feet (more or less) of 8 5/8" surface casing to assure complete coverage of both water somes, as in most cases the second water encountered in this area is very salty. Therefore, I have approved your Notice of Intention to Drill with this exception.

Yours very truly,

OIL CONSERVATION COMMISSION

L. A. HANSON Supervisor, Oil & Gas Inspector

LAH/1h