

NO. OF COPIES RECEIVED	5
DISTRIBUTION	
SANTA FE	1
FILE	1
U.S.G.S.	
LAND OFFICE	
OPERATOR	3

NEW MEXICO OIL CONSERVATION COMMISSION

Form C-103
Supersedes Old
C-102 and C-103
Effective 1-1-65

3
2 1969

5a. Indicate Type of Lease State <input checked="" type="checkbox"/> Fee <input type="checkbox"/>
5. State Oil & Gas Lease No. E-7179
7. Unit Agreement Name
8. Farm or Lease Name Signal State
9. Well No. 2
10. Field and Pool, or Wildcat Artesia
12. County Eddy

SUNDRY NOTICES AND REPORTS ON WELLS

(DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT -" (FORM C-101) FOR SUCH PROPOSALS.)

1. OIL WELL <input checked="" type="checkbox"/> GAS WELL <input type="checkbox"/> OTHER- <input type="checkbox"/>
2. Name of Operator Ralph Nix
3. Address of Operator P.O. Box 617 Artesia, New Mexico 88210
4. Location of Well UNIT LETTER E, 2390 FEET FROM THE North LINE AND 1050 FEET FROM THE West LINE, SECTION 17 TOWNSHIP 18 RANGE 28 NMPM.
15. Elevation (Show whether DF, RT, GR, etc.) 3610 G.L.

Check Appropriate Box To Indicate Nature of Notice, Report or Other Data
NOTICE OF INTENTION TO:

PERFORM REMEDIAL WORK ☐
TEMPORARILY ABANDON ☐
PULL OR ALTER CASING ☐
OTHER ☐

PLUG AND ABANDON ☐
CHANGE PLANS ☐

REMEDIAL WORK ☐
COMMENCE DRILLING OPNS. ☒
CASING TEST AND CEMENT JOB ☒

ALTERING CASING ☐
PLUG AND ABANDONMENT ☐

OTHER ☒ Progress report-report on casing run to shut off cave.

17. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work) SEE RULE 1103.

May 14, 1969-Marker was pulled and reentry work started. Drilled well to apprx. 210' and ran into shot up 10" casing. Ran 209.16', 8 5/8" casing to shut off cave. Continued to drill shot up casing to around 300'. Hole started to go at this point, but with considerable cave. Driled well to 403', then ran 403' 7" casing to shut off cave. Drilled from 403' to 450' of shot up casing, then well started going again. Cleaned well out to 2165'.
June 29, 1969-Ran 1883' of 4 1/2" with guide shoe and umbrella on casing, and cemented with 100 sacks. Waited 24 hours.
6-30-69-Started drilling umbrella. Tested well, had good cement job. Clean well back to 2150'.
7-31-69-Ran 2110' of 2" upset tubing and began testing.

18. I hereby certify that the information above is true and complete to the best of my knowledge and belief.

SIGNED Joe Lopez

TITLE Agent

DATE 7-2-69

APPROVED BY W.A. Gressett

TITLE OIL AND GAS INSPECTOR

DATE JUL 3 1969

CONDITIONS OF APPROVAL, IF ANY: