NO. OF COPIES MECEIVED	<u> </u>				•	Form C-103	•		
DISTRIBUTION									
SANTA FE		INEW MEX	ICO OIL CONSE						
FILE	1			RECEIVED	-				
U.S.G.S.	1					(-43)	, —		
LAND OFFICE			1	NIIC 9 9 1090	L		Feo.		
OPERATOR	1]		400 & J 1300	, · [5. State Oli & Cas	Lease No.		
				000	2				
' (OO NOT USE THIS FOR Use	SUND!	RY NOTICES AND FOR TOO TION FOR PERMIT -" (FOR	REPORTS ON DECPEN OF PLUG BA	WELLS ARTHOSIAO, PEREGERESERVOIR PROPOSSALS.)		7. Unit Agreement	Name		
WELL LXJ WELL		OTHER-	·						
Name of Operator Yates Drilling Company Address of Operator 207 S. 4th, Artesia, NM 88210 Location of Well West Line, Section 19 Township 18S RANCE 28E NAMPM. 15. Elevation (Show whether DF, RT, GR, etc.) 3586 GR Check Appropriate Box To Indicate Nature of Notice, Report or Other Data NOTICE OF INTENTION TO: SUBSEQUENT REPORT OF: CASING TEST AND GENERAL WORK COMMENCE DRILLING DPHS. CASING TEST AND GENERAL JUB CASING OTHER Bradenhead Test Dug out bradenhead. Installed 2" high pressure nipples with 2" high pressure valve. Brought above ground level. Swidged down w/tapped ball plug and ½" needle valve. Bradenhead or casing, Tubing pressure 850. Inspected by									
	Attesia Metex Unit s of Operator Yates Drilling Company Artesia, NM 88210 207 S. 4th, Artesia, NM 88210 1 #12 10. Field and Pool, or Wildest Artesia Grig. SA West Line, Section 19 Township 18S RANGE 28E NMPM. 15. Elevation (Show whether DF, RT, GR, etc.) 3586 GR Check Appropriate Box To Indicate Nature of Notice, Report or Other Data NOTICE OF INTENTION TO: REMEDIAL WORK ALTERIAG CASING PLUG AND ABANDON ALTER CASING CHANCE PLANS CHANCE PLANS CHANCE PLANS CHANCE PLANS CHANCE PLANS CHANCE PLANS Dug out bradenhead. Installed 2" high pressure nipples with 2" high pressure valve. Brought above ground level. Swidged down w/tapped ball plug and ½" needle valve. Bradenhead and casing shut in 24 hours before inspection.						ex Unit		
. Address of Operator									
	AUG 29 1980 AUG 29 1980 AUG 29 1980 Sol. Indicant Type of Leader State All Fee Stat					11 1 2			
. Location of Well									
UNIT LETTER K		1650" FEET FROM T	HE South	LINE AND	FEET FROM	Artesia Grbo	J. SA		
			•		NMPM.				
mmm	7777	15. Elevatic	n (Show whether I	OF, RT, GR, etc.)		12, County	X111111X		
		//////	_						
· · · · · · · · · · · · · · · · · · ·	77777				L		<i>177777777</i> 7		
•			o Indicate Na	=					
_	ו						Г		
PERFORM REMEDIAL WORK] 1	. PLUG A	NO ABANDON		님 '	•	-		
TEMPORARILY ABAHDON	1	,			님	PLUG AN	_ тизмиосиках С		
PULL OR ALTER CASING	j	CHANGE	PLANS			+	13		
				OTHER DECUCIO	eau <u>res</u>	<u>L</u>	Ľ		
OTHER									
	mpleted (perations (Clearly state	all pertinent deta	ils, and give pertinent dates,	including e	stimated date of st	tarting any propos		
BOIN SEE ROLE 11031							•		
valve. Bro needle valv No pressure	ought ve. E e on k	above ground le Bradenhead and c oradenhead or c	vel. Swidg casing shut	ed down w/tapped h in 24 hours befor	oall plu ce inspe	g and ½" ction.			
				,					
				•		•			
				•					
•			. •	· ·					
		•							
•		,				·			
8. I hereby certify that the i	informatio	n above is true and comp	olete to the best o	f my knowledge and belief.					
1		· · · · · · · · · · · · · · · · · · ·		,					
b. Ma	w		TITLE	Drilling Supervis	sor	DATE Augus	st 28, 1980		
TURED /									
B.4). U	Leever	TITLE	OIL AND GAS INSPECT	OB	DATE SI	EP 8 - 1980		

CONDITIONS OF APPROVAL, IF ANY: