

Jim's Water Service of New Mexico

A Division of Jim's Water Service of Colorado, Inc.

RECEIVED

JUN 17 1992

O. C. D.
Office

P. O. Box 848
Artesia, New Mexico 88210
(505) 748-1352
Roswell, New Mexico 88201
(505) 622-9790
FAX (505) 746-3227

M-19609 State 24 Well #1
Completion Report

Follow up reports and results of report C-103 dated 6-22-92.

June 23, 1992 Tuesday

Upon pulling 2 7/8 tubing, it was found to have been cut off at 434.80'. This is approximately 18' below the 8 5/8 pipe. Picked up new string of 2 7/8 tubing, 7 5/8 bit, and 8 5/8 casing scraper. Went in the hole to a depth of 387'. The scraper caught on something and it was believed to be a bad spot in the 8 5/8 pipe. Pulled out of the hole and ran 8 5/8 bridge plug to test 8 5/8 casing. The test was inconclusive.

June 24, 1992 Wednesday

Continued to try to test 8 5/8 with 8 5/8 packer and bridge plug. Tested every 30 ft. from the bottom up. The pressure leaked off. Leakage due somewhat to no packer seats. However, at 134' from the surface, determined a probable leak in 8 5/8 pipe. Pulled out of the hole and laid down the assembly and returned to bottom open ended with 2 7/8 tubing, set a 40 sack cement plug. Shut down for WOC.

June 25, 1992 Thursday

Ran in hole with 7 7/8" bit to tag plug. No plug found. Pulled out of hole and ran 8 5/8 bridge plug with a by pass. Set bridge plug at 381'. Got packer seat, pumped 21 bbls fresh water at 5 bbls per minute. Felt fluid was going out hole in 8 5/8" pipe at 134'. Shut down for the day.

June 26, 1992 Friday

Rigged up dump bailer, pushed a 8 5/8" rubber wiper plug to 400'. Used dump bailer and put 6 sacks of cement and 2 sacks of sand on top of the rubber plug. Tagged plug at 378'. Shut down WOC.

June 29, 1992 Monday

Went in hole with 7 7/8" bit to tag plug. "No Plug".
Shut down.