

## OIL CONSERVATION COMMISSION

Santa Fe, New Mexico

## MISCELLANEOUS REPORTS ON WELLS

Submit this report in triplicate to the Oil Conservation Commission or its proper agent within ten days after the work specified is completed. It should be signed and sworn to before a notary public for reports on beginning drilling operations, results of shooting well, results of test of casing shut off, result of plugging of well, and other important operations, even though the work was witnessed by an agent of the Commission. Reports on minor operations need not be signed and sworn to before a notary public. See additional instructions in the Rules and Regulations of the Commission.

Indicate nature of report by checking below.

REPORT ON BEGINNING DRILLING OPERATIONS		REPORT ON REPAIRING WELL	
REPORT ON RESULT OF SHOOTING OR CHEMICAL TREATMENT OF WELL		REPORT ON PULLING OR OTHERWISE ALTERING CASING	
REPORT ON RESULT OF TEST OF CASING SHUT-OFF		REPORT ON DEEPENING WELL	
REPORT ON RESULT OF PLUGGING OF WELL	<b>X</b>		

March 24, 1948

Artesia, N. Mex.

Date

Place

OIL CONSERVATION COMMISSION,  
SANTA FE, NEW MEXICO.

Gentlemen:

Following is a report on the work done and the results obtained under the heading noted above at the G. A. Grober

Company or Operator SE 1/4 NW 1/4 of Sec. 25, T. 18S, R. 28E, N. M. P. M.,  
wildcat Field, Eddy County.

The dates of this work were as follows: February and March 1948

Notice of intention to do the work was ~~(was not)~~ submitted on Form C-102 on March 19 48  
 and approval of the proposed plan was ~~(was not)~~ obtained. (Cross out incorrect words.)

## DETAILED ACCOUNT OF WORK DONE AND RESULTS OBTAINED

Bridge in hole at 1400' was drilled out and hole bailed dry, then hole was cleaned out to 1750'. At that point solid iron was encountered and it was drilled on for several days without making any progress. A test was made to determine if the hole made any water, and no water was found. A cement plug of 3 sacks was set at this point. The hole was mudded back to 1400' and a bridge and cement plug of 3 sacks set at this point. The hole was then mudded back to 1070' and a cement plug of 3 sacks set at this point on a bridge. Hole was mudded back to 650' and bridge and cement plug of 3 sacks set. The casing was knocked off at 350' and hole was mudded to this point and bridge and cement plug of 3 sacks set. The hole was then mudded back to the surface and the regulation marker of 4" pipe was set in cement.

Name Harold Kersey Company Kersey & Co. Title Partner

Subscribed and sworn before me this 24th

I hereby swear or affirm that the information given above is true and correct.

day of March, 19 48Name Harold KerseyPosition PartnerRepresenting Kersey & Co., contractor on plugging job.  
Company or Operator

Notary Public

My commission expires

My Commission Expires December 30, 1948Address Box 305, Artesia, N. Mex.

Remarks:

Plugging Report compared with well logJustin Newman

Name

Artesia Petroleum Co.

Title