

NEW MEXICO OIL CONSERVATION COMMISSION
MISCELLANEOUS REPORTS ON WELLS

(Submit to appropriate District Office as per Commission Rule 1106)

COMPANY Resler & Yates et al, 302 Carper Building, Artesia, New Mexico
(Address)

LEASE State WELL NO. 92 UNIT N S 27 T 18S R 28E

DATE WORK PERFORMED September, 1956 POOL Artesia

This is a Report of: (Check appropriate block) ☐ Results of Test of Casing Shut-off
☐ Beginning Drilling Operations ☒ Remedial Work
☐ Plugging ☐ Other _____

Detailed account of work done, nature and quantity of materials used and results obtained.

Ran Gamma-neutron log. Perforated 2469-76, 2429-41, 2394-2400, 2387-2390, 2372-2378, 2302-2308 and 2181-2211. Treated five zones each w/10,000 gallons lease crude and 20,000 lbs. sand. Five zones as follows:

2469-2476
2429-2441
2394-2400, 2387-2390, 2372-2378
2302-2308
2181-2211

Put well back on production

FILL IN BELOW FOR REMEDIAL WORK REPORTS ONLY

Original Well Data:

DF Elev. _____ TD 2902 PBD _____ Prod. Int. 2800-2900 Compl Date 7-17-48
Tbng. Dia 2 Tbng Depth 2800 Oil String Dia 7 Oil String Depth 2720
Perf Interval (s) None
Open Hole Interval 2720-2902 Producing Formation (s) San Andres

RESULTS OF WORKOVER:

	BEFORE	AFTER
Date of Test	_____	<u>October 8</u>
Oil Production, bbls. per day	_____	<u>45</u>
Gas Production, Mcf per day	_____	_____
Water Production, bbls. per day	_____	<u>0</u>
Gas-Oil Ratio, cu. ft. per bbl.	_____	_____
Gas Well Potential, Mcf per day	_____	_____

Witnessed by Loree Evans

Resler & Yates et al
(Company)

OIL CONSERVATION COMMISSION

Name M. L. Armstrong
Title _____
Date _____

I hereby certify that the information given above is true and complete to the best of my knowledge.

Name Olaf R. Nelson
Position _____
Company Resler & Yates et al