




NEW MEXICO OIL CONSERVATION COMMISSION

Santa Fe, New Mexico

WELL RECORD

DECEMBER 1 1958

Mail to District Office, Oil Conservation Commission, to which Form C-101 was sent not later than twenty days after completion of well. Follow instructions in Rules and Regulations of the Commission. Submit in QUINTUPLICATE. If State Land submit 6 Copies

AREA 640 ACRES
LOCATE WELL CORRECTLY

Kersey & Company
(Company or Operator)

Featherstone
(Lease)

Well No. 2, in 34 1/4 of 34 1/4, of Sec. 29, T. 18, R. 23, NMPM.

Artesia Pool, Eddy County.

Well is 1060 feet from North line and 250 feet from East line

of Section 29. If State Land the Oil and Gas Lease No. is B. 6911

Drilling Commenced, 19, Drilling was Completed July 20, 1958

Name of Drilling Contractor Kersey & Company

Address Box 305, Artesia, New Mexico

Elevation above sea level at Top of Tubing Head The information given is to be kept confidential until 19

OIL SANDS OR ZONES

No. 1, from 1994 to 2004 No. 4, from 2126 to 2132

No. 2, from 2053 to 2058 No. 5, from 2176 to 2184

No. 3, from 2108 to 2214 No. 6, from 2228 to 2236

IMPORTANT WATER SANDS

Include data on rate of water inflow and elevation to which water rose in hole.

No. 1, from to feet.

No. 2, from to feet.

No. 3, from to feet.

No. 4, from to feet.

CASING RECORD

SIZE	WEIGHT PER FOOT	NEW OR USED	AMOUNT	KIND OF SHOE	CUT AND PULLED FROM	PERFORATIONS	PURPOSE
8 5/8	24#		555				
5 1/2	14#		2261				

MUDDING AND CEMENTING RECORD

SIZE OF HOLE	SIZE OF CASING	WHERE SET	NO. SACKS OF CEMENT	METHOD USED	MUD GRAVITY	AMOUNT OF MUD USED
10	8 5/8	555	50			
8	5 1/2	2261	80			

RECORD OF PRODUCTION AND STIMULATION

(Record the Process used, No. of Qts. or Gals. used, interval treated or shot.)

Fractured with 50,000# (River Frac) Sand.

2228 - 36 ; 2176 - 84 ; 2053 - 58 ; 2108 - 14 ; 2126 - 32 ; 1994 - 2004

Result of Production Stimulation Production natural test 1 gal/hour.

Production after treatment 30 bbl/day

Depth Cleaned Out

LOG OF DRILL-STEM AND SPECIAL TESTS

If drill-stem or other special tests or deviation surveys were made, submit report on separate sheet and attach hereto

TOOLS USED

Rotary tools were used from _____ feet to _____ feet, and from _____ feet to _____ feet.
 Cable tools were used from 2130 feet to 2457 feet, and from _____ feet to _____ feet.

PRODUCTION

Put to Producing July 20, 1958

OIL WELL: The production during the first 24 hours was _____ barrels of liquid of which _____ % was
 was oil; _____ % was emulsion; _____ % water; and _____ % was sediment. A.P.I.
 Gravity _____

GAS WELL: The production during the first 24 hours was _____ M.C.F. plus _____ barrels of
 liquid Hydrocarbon. Shut in Pressure _____ lbs.

Length of Time Shut in _____

PLEASE INDICATE BELOW FORMATION TOPS (IN CONFORMANCE WITH GEOGRAPHICAL SECTION OF STATE):

Southeastern New Mexico		Northwestern New Mexico	
T. Anhy.....	T. Devonian.....	T. Ojo Alamo.....	
T. Salt.....	T. Silurian.....	T. Kirtland-Fruitland.....	
B. Salt.....	T. Montoya.....	T. Farmington.....	
T. Yates.....	T. Simpson.....	T. Pictured Cliffs.....	
T. 7 Rivers.....	T. McKee.....	T. Menefee.....	
T. Queen.....	T. Ellenburger.....	T. Point Lookout.....	
T. Grayburg.....	T. Gr. Wash.....	T. Mancos.....	
T. San Andres.....	T. Granite.....	T. Dakota.....	
T. Glorieta.....	T.	T. Morrison.....	
T. Drinkard.....	T.	T. Penn.....	
T. Tubbs.....	T.	T.	
T. Abo.....	T.	T.	
T. Penn.....	T.	T.	
T. Miss.....	T.	T.	

FORMATION RECORD

From	To	Thickness in Feet	Formation	From	To	Thickness in Feet	Formation
21			GETTING DEEPER				
2130	2168		Gray lime				This was an old well on that has been plugged and abandoned for many years. We cleaned it out and drilled from 2130' to 2457'
2168	2178		Gray lime & sand				
			Sample shows oil -				
			No free oil added to hole				
2178	2196		Gray lime				
2196	2209		White lime				
2209	2230		Gray lime				
2230	2238		Pink lime				
			Sand lime - oil show				
			(Premier)				
			tested 1 gal of oil/hr.				
2238	2255		Pink lime				
2255	2265		Pink & Red lime				
2265	2290		Pink lime				
2290	2365		White lime				
			Top San Andreas 2290				
2365	2373		Gray lime				
2373	2391		Brown lime				
2391	2430		Gray lime				
2430	2449		Gray lime & sand				
			(Lovington Sand)				
2449	2457		Gray lime				
	2457		T. D.				

ATTACH SEPARATE SHEET IF ADDITIONAL SPACE IS NEEDED

I hereby swear or affirm that the information given herewith is a complete and correct record of the well and all work done on it so far
 as can be determined from available records.

Company or Operator Kersey & Company
 Name Harold Kersey

Address Box 305, Artesia, New Mexico
 Position or Title Partner

(Date)