

Submit 3 Copies
to Appropriate
District Office

State of New Mexico
Energy, Minerals and Natural Resources Department

RECEIVED Form C-103
Revised 1-1-89

DISTRICT I
P.O. Box 1980, Hobbs, NM 88240

DISTRICT II
P.O. Drawer DD, Artesia, NM 88210

DISTRICT III
1000 Rio Brazos Rd., Aztec, NM 87410

OIL CONSERVATION DIVISION

P.O. Box 2088
Santa Fe, New Mexico 87504-2088

WELL API NO. JUN 14 '90

5. Indicate Type of Lease
☒ STATE ☐ FEE

6. State Oil & Gas Lease No. 647

SUNDRY NOTICES AND REPORTS ON WELLS
(DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A
DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT"
(FORM C-101) FOR SUCH PROPOSALS.)

1. Type of Well:
OIL WELL ☒ GAS WELL ☐ OTHER

2. Name of Operator
Arch Petroleum Inc.

7. Lease Name or Unit Agreement Name

Resler-Yates State

3. Address of Operator
Suite IIA; 777 Taylor St.; Ft. Worth, Tx 76102

8. Well No. 61

9. Pool name or Wildcat
Artesia QN-GB-SA

4. Well Location
Unit Letter C : 2380 Feet From The West Line and 1060 Feet From The North Line

Section 32 Township 18S Range 28E NMPM Eddy County

10. Elevation (Show whether DF, RKB, RT, GR, etc.)

11. Check Appropriate Box to Indicate Nature of Notice, Report, or Other Data

NOTICE OF INTENTION TO:

PERFORM REMEDIAL WORK ☐

PLUG AND ABANDON ☐

TEMPORARILY ABANDON ☐

CHANGE PLANS ☐

PULL OR ALTER CASING ☐

OTHER: ☐

SUBSEQUENT REPORT OF:

REMEDIAL WORK ☒ ALTERING CASING ☐

COMMENCE DRILLING OPNS. ☐ PLUG AND ABANDONMENT ☐

CASING TEST AND CEMENT JOB ☐

OTHER: ☐

12. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work) SEE RULE 1103.

6/4/90 - MIRU workover unit. Pulled rods and tubing. Ran 6 1/4 bit and cleaned out hole to 2010'.

6/5/90 - Ran CBL over 8 1/4 casing. Showed GOOD bonding from bottom of 8 1/4 to 482'. Ran 4 1/2 9.50# casing to 1988'. Cemented with Halliburton out of Artesia. Pumped 525SX. Circulated 81SX to pit. SDON.

6/6/90 - Cut off 4 1/2 casing and welded on bell nipple. Ran into hole with 3 7/8 bit. Tagged cement @ 1940'. Drilled float collar, shoe joint and guide show. Cleaned out to 2032'.

6/7/90 - Fraced well down casing with western co. out of Hobbs, New Mexico. Pumped 20,000 gal gel and 46,000 # sand.

6/8/90 - Ran rods and tubing. Placed well on production.

I hereby certify that the information above is true and complete to the best of my knowledge and belief.

SIGNATURE Jim B. Paschall TITLE V. P. Operations DATE June 12, 1990

TYPE OR PRINT NAME Jim B. Paschall 817 332 9209 TELEPHONE NO.

(This space for State Use)

ORIGINAL SIGNED BY
MIKE WILLIAMS
SUPERVISOR, DISTRICT II

APPROVED BY TITLE DATE JUN 19 1990

CONDITIONS OF APPROVAL, IF ANY: