

NEW MEXICO OIL CONSERVATION COMMISSION

MISCELLANEOUS REPORTS ON WELLS

FORM C-103
(Rev 3-55)

(Submit to appropriate District Office as per Commission Rule 1706)

1960

Name of Company Granridge Corporation		Address Box 752, Breckenridge, Texas			
Lease Resler Yates State	Well No. 6	Unit Letter D	Section 32	Township 18S	Range 28E
Date Work Performed See Below	Pool Artesia			County Eddy	

THIS IS A REPORT OF: (Check appropriate block)

- ☐ Beginning Drilling Operations ☐ Casing Test and Cement Job ☒ Other (Explain):
☐ Plugging ☐ Remedial Work See Below

Detailed account of work done, nature and quantity of materials used, and results obtained.

7-23-60 Ran a total of 1861.17' of 2" EUE 8 Rd. Thd cement lined tubing with Guiberson Shorty tension packer. Set packer at 1861' to run Iso-flow survey.

9-10-60 Ran Welox, Inc. Iso-flow Survey.

COPY

Witnessed by Paul Darnell	Position Superintendent	Company Granridge Corporation
------------------------------	----------------------------	----------------------------------

FILL IN BELOW FOR REMEDIAL WORK REPORTS ONLY

ORIGINAL WELL DATA

D F Elev.	T D	P BTD	Producing Interval	Completion Date
Tubing Diameter	Tubing Depth	Oil String Diameter	Oil String Depth	
Perforated Interval(s)				
Open Hole Interval		Producing Formation(s)		

RESULTS OF WORKOVER

Test	Date of Test	Oil Production BPD	Gas Production MCFPD	Water Production BPT	GOR Cubic feet/Bbl	Gas Well Potential MCFPD
Before Workover						
After Workover						

OIL CONSERVATION COMMISSION		I hereby certify that the information given above is true and complete to the best of my knowledge.	
Approved by <i>ML Armstrong</i>	Name <i>Charles W. Smith</i>		
Title DISTRICT ENGINEER	Position Charles W. Smith Production Clerk		
Date OCT 9 1960	Company Granridge Corporation		

[illegible]