

NUMBER OF COPIES RECEIVED	
DISTRIBUTION	
SANTA FE	
FILE	
U.S.G.S	
LAND OFFICE	
TRANSPORTER	OIL
	GAS
PRODUCTION OFFICE	
OPERATOR	

NEW MEXICO OIL CONSERVATION COMMISSION

FORM C-103
(Rev 3-55)

MISCELLANEOUS REPORTS ON WELLS

(Submit to appropriate District Office as per Commission Rule 1106)

Name of Company Kersey & Company ✓		Address P. O. Box 316, Artesia, New Mexico	
Lease Yates ✓	Well No. 6 ✓	Unit Letter F ✓	Section 33 ✓
Township 18S ✓		Range 28E ✓	
Date Work Performed January 25, 1965	Pool Artesia Field ✓	County Eddy	

THIS IS A REPORT OF: (Check appropriate block)

- ☐ Beginning Drilling Operations
 ☐ Casing Test and Cement Job
 ☐ Other (Explain):
- ☒ Plugging
 ☐ Remedial Work

Detailed account of work done, nature and quantity of materials used, and results obtained.

Cleaned out to 2515'. Unable to proceed to get to bottom at 2750'.
Set 20 sack cement plug at 2515'. Mudded hole to surface. Set 20 sack cement plug at 790'. Set marker in concrete at surface.

RECEIVED

FEB 16 1965

O. C. C.
ARTESIA, OFFICE

Witnessed by	Position	Company
--------------	----------	---------

FILL IN BELOW FOR REMEDIAL WORK REPORTS ONLY

ORIGINAL WELL DATA

D F Elev.	T D	P B T D	Producing Interval	Completion Date
Tubing Diameter	Tubing Depth	Oil String Diameter	Oil String Depth	
Perforated Interval(s)				
Open Hole Interval		Producing Formation(s)		

RESULTS OF WORKOVER

Test	Date of Test	Oil Production BPD	Gas Production MCFPD	Water Production BPD	GOR Cubic feet/Bbl	Gas Well Potential MCFPD
Before Workover						
After Workover						

OIL CONSERVATION COMMISSION		I hereby certify that the information given above is true and complete to the best of my knowledge.	
Approved by <i>W. L. Armstrong</i>	Name <i>Harold Kersey</i>		
Title	Position Owner		
Date	Company KERSEY & COMPANY		