

OF COPIES RECEIVED	3
DISTRIBUTION	
SA A FE	1
FILE	1
U.S.G.S.	
LAND OFFICE	
OPERATOR	1

RECEIVED
NEW MEXICO OIL CONSERVATION COMMISSION
AUG 16 1977
D. C. C.
ARTESIA, OFFICE

Form C-103
 Supersedes Old
 C-102 and C-103
 Effective 1-1-65

5a. Indicate Type of Lease State <input checked="" type="checkbox"/> Fee <input type="checkbox"/>
5. State Oil & Gas Lease No.
7. Unit Agreement Name Artesia, Unit
8. Farm or Lease Name
9. Well No. 39
10. Field and Pool, or Wildcat Artesia
12. County Eddy

SUNDRY NOTICES AND REPORTS ON WELLS
(DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT -" (FORM C-101) FOR SUCH PROPOSALS.)

1. ☒ OIL WELL ☐ GAS WELL ☐ OTHER-

2. Name of Operator
DEPCO, Inc.

3. Address of Operator
800 Central, Odessa, Texas 79761

4. Location of Well
 UNIT LETTER **C**, **992** FEET FROM THE **N** LINE AND **2275** FEET FROM
 THE **W** LINE, SECTION **3** TOWNSHIP **18s** RANGE **28e** NMPM.

15. Elevation (Show whether DF, RT, GR, etc.)
3670 Gr.

16. Check Appropriate Box To Indicate Nature of Notice, Report or Other Data

NOTICE OF INTENTION TO:	SUBSEQUENT REPORT OF:
PERFORM REMEDIAL WORK <input type="checkbox"/>	REMEDIAL WORK <input checked="" type="checkbox"/>
TEMPORARILY ABANDON <input type="checkbox"/>	COMMENCE DRILLING OPNS. <input type="checkbox"/>
PULL OR ALTER CASING <input type="checkbox"/>	CASING TEST AND CEMENT JOBS <input type="checkbox"/>
OTHER <input type="checkbox"/>	OTHER <input type="checkbox"/>
PLUG AND ABANDON <input type="checkbox"/>	ALTERING CASING <input type="checkbox"/>
CHANGE PLANS <input type="checkbox"/>	PLUG AND ABANDONMENT <input type="checkbox"/>

17. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work) SEE RULE 1103.

7-14-77 Hole & tight spot found in csg. from 1680-1685'. The tight spot was swaged out and the well was plugged back to 2319' with frac sand. A packer was then set at 2001' and the csg. shoe was then squeezed with 100 sx. Class C cmt. Reset packer at 1410' and squeezed hole with 200 sx. Class C cmt. Drilled out cmt. & returned to production.

18. I hereby certify that the information above is true and complete to the best of my knowledge and belief.

SIGNED *Dean Steward* TITLE Engineer Assistant DATE 8-15-77

APPROVED BY *W. A. Gressett* TITLE SUPERVISOR, DISTRICT II DATE AUG 24 1977

CONDITIONS OF APPROVAL, IF ANY: