

NEW MEXICO OIL CONSERVATION COMMISSION
MISCELLANEOUS REPORTS ON WELLS

(Submit to appropriate District Office as per Commission Rule 1106)

COMPANY Malco Resler Yates, 304 Carper Building, Artesia, New Mexico
(Address)

LEASE State WELL NO. 127 UNIT B S 3 T 18 R 28

DATE WORK PERFORMED Jan. 16 - 20, 1956 POOL Artesia

This is a Report of: (Check appropriate block) ☒ Results of Test of Casing Shut-off

☐ Beginning Drilling Operations

☐ Remedial Work

☐ Plugging

☐ Other _____

Detailed account of work done, nature and quantity of materials used and results obtained.

Drilled to 510'. Set 7" casing @ 510! w/100 sax. Let stand 72 hours and drilled out plugs. Water shut off, so resumed drilling.

FILL IN BELOW FOR REMEDIAL WORK REPORTS ONLY

Original Well Data:

DF Elev. _____ TD _____ PBD _____ Prod. Int. _____ Compl Date _____

Tbng. Dia _____ Tbng Depth _____ Oil String Dia _____ Oil String Depth _____

Perf Interval (s) _____

Open Hole Interval _____ Producing Formation (s) _____

RESULTS OF WORKOVER:

BEFORE

AFTER

Date of Test

Oil Production, bbls. per day

Gas Production, Mcf per day

Water Production, bbls. per day

Gas-Oil Ratio, cu. ft. per bbl.

Gas Well Potential, Mcf per day

Witnessed by Miller

S. P. Yates Drilling Company
(Company)

OIL CONSERVATION COMMISSION

Name

P. A. Johnson

Title

Date

I hereby certify that the information given above is true and complete to the best of my knowledge.

Name

Vito P. Skelton

Position

Sec. Oper. Comm

Company

Malco Resler Yates