NEW MEXICO OIL CONSERVATION COMMISSION

FORM C-103 (Rev 3-55)

MISCELLANEOUS REPORTS ON WELLS DEC 2 8 1959										
		(Submit to appro	priate District Of	fice as pe	r Comm	nission Rul	• 1106			
Name of Company Resler and Sheldon					Address 302 Curper Building, Artesia, New Mexico					
Lease	State		Well No. Unit	Letter S	6	Township	186	Range	28g	
Date Work Pe	rformed	Pool	· Alo Lend	221		County	ly .		,	
THIS IS A REPORT OF: (Check appropriate block)										
Beginning Drilling Operations Casing Test and Cement Job Completion										
Plugging Remedial Work Detailed account of work done, nature and quantity of materials used, and results obtained.										
	bubing to 50	675' with pack	ter on bottom	. Sot 1	pacita	r >615.•	and	Beef Acity		
Witnessed by Position					Company Vilas P. Sheldon					
FILL IN BELOW FOR REMEDIAL WORK REPORTS ONLY										
D F Elev.		D	PBTD	PBTD		Producing Interv		val Completion Date		
Tubing Diameter		Tubing Depth		Oil String Diam		ter		Oil String Depth		
Perforated In	terval(s)	<u>,</u>		1						
Open Hole Interval					Producing Formation(s)					
			RESULTS O	FWORK	OVER	~~~~~~~~~~~~~~~~~~~~~~~~~~~~~~~~~~~~~~				
Test	Date of Test	Oil Producti BPD	on Gas Produ MCFP					GOR feet/Bbl	Gas Well Potential MCFPD	
Before Workover										
After Workover										
OIL CONSERVATION COMMISSION					I hereby certify that the information given above is true and complete to the best of my knowledge.					
Approved by 11/ Synstyona			lug	Name Vilas Phillor						
					Position Pertner					
Date DEC 2 8 1959				Compan	Company Realer and Shelden					

. .

+ 4

¥