

Submit 3 Copies To Appropriate District
Office
District I
1625 N. French Dr., Hobbs, NM 88240
District II
811 South First, Artesia, NM 88210
District III
1000 Rio Brazos Rd., Aztec, NM 87410
District IV
2040 South Pacheco, Santa Fe, NM 87505

State of New Mexico
Energy, Minerals and Natural Resources

OIL CONSERVATION DIVISION
2040 South Pacheco
Santa Fe, NM 87505

CISF

Form C-103
Revised March 25, 1999

SUNDRY NOTICES AND REPORTS ON WELLS (DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT" (FORM C-101) FOR SUCH PROPOSALS.)	
1. Type of Well: Oil Well <input type="checkbox"/> Gas Well <input type="checkbox"/> Other <u>Water Injection well</u>	WELL API NO. <u>30-015-02655-00-00</u>
2. Name of Operator <u>B&W Oil Company Inc.</u>	5. Indicate Type of Lease STATE <input checked="" type="checkbox"/> FEE <input type="checkbox"/>
3. Address of Operator <u>R-252 No. Haldeman Rd. Artesia, New Mex. 88210</u>	6. State Oil & Gas Lease No. <u>E7179</u>
4. Well Location Unit Letter <u>K</u> : <u>1650</u> feet from the <u>South</u> line and <u>1650</u> feet from the <u>West</u> line Section <u>8</u> Township <u>18S</u> Range <u>28E</u> NMPM County <u>Eddy</u>	7. Lease Name or Unit Agreement Name: <u>West Artesia Grbg Unit</u>
10. Elevation (Show whether DR, RKB, RT, GR, etc.) <u>No Record 3603</u>	8. Well No. <u>11</u>
	9. Pool name or Wildcat <u>Artesia-Qn-GB-SA</u>

11. Check Appropriate Box to Indicate Nature of Notice, Report or Other Data

NOTICE OF INTENTION TO:

- PERFORM REMEDIAL WORK ☐ PLUG AND ABANDON ☐
TEMPORARILY ABANDON ☐ CHANGE PLANS ☐
PULL OR ALTER CASING ☐ MULTIPLE COMPLETION ☐
OTHER: Repair Tubin Leak ☒

SUBSEQUENT REPORT OF:

- REMEDIAL WORK ☐ ALTERING CASING ☐
COMMENCE DRILLING OPNS. ☐ PLUG AND ABANDONMENT ☐
CASING TEST AND CEMENT JOB ☐
OTHER: Repair Tubin Leak ☒

12. Describe proposed or completed operations. (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work). SEE RULE 1103. For Multiple Completions: Attach wellbore diagram of proposed completion or recompilation.

- 8-26-00 Moved unit to location, rigged up unit, got ready to pull tubin, shut down.
8-28-00 opened well no pressure. Started pulling tubin, found hole in 41st joint pulled packer out of hole, ran rebuilt packer and replaced 1 joint of pipe, circulated hole with packer fluid, set packer. Started well test. Pack off rubber leaked, Didn't have new rubber Tightened pack off ring. Started well test. Rubber leaking a little ran 20 plus minutes test. Returned well to injection oked test with O.C.D.

I hereby certify that the information above is true and complete to the best of my knowledge and belief.

SIGNATURE Billy J. Smith TITLE President

Type or print name Billy J. Smith

(This space for State use)

APPROVED BY Mrs. Stullfield TITLE Field Rep. II
Conditions of approval, if any:

Telephone No. 505 746-435

DATE 10-12-00

