(SUBMIT IN TRIPLICATE)

UNITED STATES THE INTERIOR GEOLOGICAL SURVEY

	Approval expires 12-31-55.
Land Office	Ar a da
Lease No	
Unit	Danishma, et d

Bureau 42-R358 3

SUNDRY NOTICES AND REPORTS ON WELLS

NOTICE OF INTENTION TO CHANGE PLANS	SUBSEQUENT REPORT OF WATER SHUT-OFF. SUBSEQUENT REPORT OF SHOOTING OR ACIDIZING. SUBSEQUENT REPORT OF ALTERING CASING. SUBSEQUENT REPORT OF RE-DRILLING OR REPAIR. SUBSEQUENT REPORT OF ABANDONMENT. SUPPLEMENTARY WELL HISTORY.

(INDICATE ABOVE BY CHECK MARK NATURE OF REPORT, NOTICE, OR OTHER DATA)

Îmaio 🖔

		, 17
Well No. is located ft. from	$n = {N \brace c}$ line and M	ft. from wine of sec.
(formedly (L-liens)	(Range) (M	ridian)
(Tiesd) county	or Subdivision)	(state or Territory)

The elevation of the derrick floor above sea level is _____ ft.


DETAILS OF WORK

(State names of and expected depths to objective sands; show sizes, weights, and lengths of proposed casings; indicate mudding jobs, cementing points, and all other important proposed work)

Not 5-1/2 tech center of 2530 fact and accepted with 60 mater of execute and placed 5-1/2 tech built play on top of the auding.

Well is temperary abandoned.

Cleatric lay is furnished beneath.



I understand that this plan of work must receive approval in writing by the Geological Survey before operations may be commenced.				
Company	School Ve Standard			
Address		By & Sward & Donohus		
	Tomas Tomas	Title		

and the control of t The control of the control of

and the state of t

and the first of the second of

•

and the control of th