

APPROVED

JUL 15 1963

RONNIE E. SHOOK
ACTING DISTRICT ENGINEER

(SUBMIT IN TRIPLICATE)

UNITED STATES
DEPARTMENT OF THE INTERIOR
GEOLOGICAL SURVEY

Land Office _____

Lease No. 44-1514-1 (a)

Unit _____

RECEIVED
JUL 16 1963**SUNDRY NOTICES AND REPORTS ON WELLS**

NOTICE OF INTENTION TO DRILL		SUBSEQUENT REPORT OF WATER SHUT-OFF	
NOTICE OF INTENTION TO CHANGE PLANS		SUBSEQUENT REPORT OF SHOOTING OR ACIDIZING	
NOTICE OF INTENTION TO TEST WATER SHUT-OFF		SUBSEQUENT REPORT OF ALTERING CASING	
NOTICE OF INTENTION TO RE-DRILL OR REPAIR WELL		SUBSEQUENT REPORT OF RE-DRILLING OR REPAIR	
NOTICE OF INTENTION TO SHOOT OR ACIDIZE		SUBSEQUENT REPORT OF ABANDONMENT	
NOTICE OF INTENTION TO PULL OR ALTER CASING		SUPPLEMENTARY WELL HISTORY	
NOTICE OF INTENTION TO ABANDON WELL		Fracture	X

(INDICATE ABOVE BY CHECK MARK NATURE OF REPORT, NOTICE, OR OTHER DATA)

Well No. 20 is located 150 ft. from N line and 200 ft. from E line of sec. 1
SE 1/4 NE 1/4 Sec. 10S 20 E 100W
 (1/4 Sec. and Sec. No.) (Twp.) (Range) (Meridian)
100 N. 100 New Mexico
 (Field) (County or Subdivision) (State or Territory)

The elevation of the derrick floor above sea level is _____ ft.

DETAILS OF WORK

(State names of and expected depths to objective sands; show sizes, weights, and lengths of proposed casings; indicate mudding jobs, cementing points, and all other important proposed work)

On 6-30-63 ran sand 1" and made 15 min. test from 2762-60 and 2766-71. We then fracked open 1" casing with packer set at 2620 with 1,000 gallons lease oil and 15,000 lb. 2-4 sand. We then circulated well clean and put on production. After recovering sand oil well tested 17 bbls. oil and 204 cu. ft. water.

RECEIVED
JUL 12 1963
U. S. GEOLOGICAL SURVEY
ARTESIA, NEW MEXICO

I understand that this plan of work must receive approval in writing by the Geological Survey before operations may be commenced.

Company NEWBENT OIL COMPANYAddress Box 10, El PasoArtesia, New MexicoORIGINAL SIGNED BY
H. J. LEDBETTER

By _____

Title Superintendent