

UNITED STATES
DEPARTMENT OF THE INTERIOR
GEOLOGICAL SURVEYSUBMIT IN TRIP
(Other Instructions
on Reverse Side)Form approved,
Circular No. 42 R1424,
LEASE RESERVATION AND SERIAL NO.

LC-060906

IF INDIAN, ALLOTTEE OR TRIBE NAME

SUNDRY NOTICES AND REPORTS ON WELLS

(Do not use this form for proposals to drill or to deepen or plug back to a different reservoir.
Use "APPLICATION FOR PERMIT--" for such proposals.)

1. <input type="checkbox"/> OIL WELL <input type="checkbox"/> GAS WELL <input type="checkbox"/> OTHER WIW		RECEIVED		7. UNIT AGREEMENT NAME West Loco Hills Grb #4 Sd Ut.	
2. NAME OF OPERATOR NEWMONT OIL COMPANY		MAY - 5 1978		8. FARM OR LEASE NAME Tract 16	
3. ADDRESS OF OPERATOR P.O. Box 1305, Artesia, New Mexico 88210		D. C. C.		9. WELL NO. 2	
4. LOCATION OF WELL (Report location clearly and in accordance with any State requirements. See also space 17 below.) At surface 2310' FNL & ³³⁰ 950' FWL of Section 1		ARTESIA, OFFICE		10. FIELD AND POOL, OR WILDCAT Loco Hills (2-8-8A)	
14. PERMIT NO.		15. ELEVATIONS (Show whether DF, RT, GR, etc.) 3547' GLM		11. SEC., T., R., M., OR BLK. AND SURVEY OR AREA Sec 1-T18S-R29E NMPM	
				12. COUNTY OR PARISH Eddy	
				13. STATE New Mexico	

16. Check Appropriate Box To Indicate Nature of Notice, Report, or Other Data

NOTICE OF INTENTION TO:

TEST WATER SHUT-OFF

FRACTURE TREAT

SHOOT OR ACIDIZE

REPAIR WELL

(Other)

PULL OR ALTER CASING

MULTIPLE COMPLETE

ABANDON*

CHANGE PLANS

SUBSEQUENT REPORT OF:

WATER SHUT-OFF

FRACTURE TREATMENT

SHOOTING OR ACIDIZING

(Other)

REPAIRING WELL

ALTERING CASING

ABANDONMENT*

Casing Nipple Repair

(NOTE: Report results of multiple completion on Well Completion or Recompletion Report and Log form.)

17. DESCRIBE PROPOSED OR COMPLETED OPERATIONS (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work. If well is directionally drilled, give subsurface locations and measured and true vertical depths for all markers and zones pertinent to this work.)*

4/24/78 -- The 7" casing nipple above the braden head was repaired and hole filled in around casing.

RECEIVED
MAY 2 1978
U.S. GEOLOGICAL SURVEY
ARTESIA, NEW MEXICO

18. I hereby certify that the foregoing is true and correct

SIGNED

TITLE

Office Manager

DATE 5/1/78

(This space for Federal or State office use)

APPROVED BY

TITLE

ACTING DISTRICT ENGINEER

DATE

MAY 4 - 1978

CONDITIONS OF APPROVAL, IF ANY: