

ILLEGIBLE

(SUBMIT IN TRIPLICATE)

UNITED STATES
DEPARTMENT OF THE INTERIOR
GEOLOGICAL SURVEY

Land Office: Las Vegas
Lessor No.: 158521
Date: 11/1/47

SUNDRY NOTICES AND REPORTS ON WELLS

NOTICE OF INTENTION TO DRILL	SUBSEQUENT REPORT OF ABANDONMENT
NOTICE OF INTENTION TO CHANGE PLANS	SUBSEQUENT REPORT OF SHUTTING IN WELL
NOTICE OF INTENTION TO TEST WATER SHUT-IN	SUBSEQUENT REPORT OF ALTERING CASING
NOTICE OF INTENTION TO RE-DRILL OR REPAIR WELL	SUBSEQUENT REPORT OF RE-DRILLING OR REPAIRING
NOTICE OF INTENTION TO SHUT IN OR ACIDIZE	SUBSEQUENT REPORT OF ABANDONMENT
NOTICE OF INTENTION TO PUMP UP AFTER CANN	SUPPLEMENTARY WELL HISTORY
NOTICE OF INTENTION TO ABANDON WELL	

NOTE: IN FILLING IN, GIVE FULL NAME AND NATURE OF REPORT, NOTICE, AND OTHER DATA.

Artesia, New Mexico

Well No. 1 is located 1.0 ft. from N line and 600 ft. from E line of sec. 3
T14N, R10E, S1E, 183 275 144PH

Owner: 144y
County or subdivision: 144y

The elevation of the derrick floor above sea level is ft

DETAILS OF WORK

State names of all extended depths to objective sands, show sizes, weights, and lengths of proposed casings, indicate shut-in points, and all other important proposed work.

This well was plugged and abandoned on 11/1/47. Work was done as follows:
Runners: From a total amount of 385' of surface pipe 111' was removed leaving 274' in hole. This pipe was filled with heavy mud and a plug of 5 sacks of cement was set. From 275' of oil string 1094' was recovered leaving 1294' in hole. This pipe was filled with heavy mud and a plug of 15 sacks of cement was set. Hole was filled with heavy mud to top where plug of 5 sacks of cement was set. Cement regulation survey was placed and well was abandoned.

Understand that approval of work must receive approval in writing by the Geological Survey before operations may be commenced.

Company: 144y

Address: 144y

Artesia, New Mexico

By

Title: 144y

