

ARTESIA OFFICE COPY
UNITED STATES
DEPARTMENT OF THE INTERIOR
GEOLOGICAL SURVEY
SANTA FE, NEW MEXICO

Copy to SF

ILLECIBLE

August 6, 1947

G. B. Suppes
P. O. Box 151
Artesia, New Mexico

Ref. L.S. 65879

Dear Sir:

Your "Subsequent Report of Abandonment" dated May 26, 1947, covering your No. 1 Miller well, located 2515 feet from the north line and 1651 feet from the east line of section 6, T. 18N., R. 9E., Los Hills Field, Bixby County, New Mexico, is hereby approved.

Yours very truly

JOHN A. FROST
District Engineer

FWB:jn
Suggested by John A. Frost
August 9, 1947

RECEIVED

MAR 12 1964

D. C. C.
ARTESIA OFFICE



(SUBMIT IN TRIPLICATE)

Local Office L.A. C-12888

License No. 058579

Name Miller

ILLECIBLE

UNITED STATES
DEPARTMENT OF THE INTERIOR
GEOLOGICAL SURVEY

SUNDRY NOTICES AND REPORTS ON WELLS

NOTICE OF INTENTION TO DRILL	SUBSEQUENT REPORT OF WATER SHUT-OFF
NOTICE OF INTENTION TO CHANGE PLANT	SUBSEQUENT REPORT OF DRIFTING OR ACCORDING
NOTICE OF INTENTION TO TEST WATER SHUT-OFF	SUBSEQUENT REPORT OF ALTERING CHARGE
NOTICE OF INTENTION TO RE-DRILL OR REPAIR WELL	SUBSEQUENT REPORT OF REMEDIAL OR REPAIR
NOTICE OF INTENTION TO CEMENT OR ABANDON	SUBSEQUENT REPORT OF ABANDONMENT
NOTICE OF INTENTION TO PULL OR ALTER CABLE	SUPPLEMENTARY WELL HISTORY
NOTICE OF INTENTION TO ABANDON WELL	

(Indicate above by check mark nature of report, notice, or other data)

May 25 1947

19

Well No. 4 is located 2313 ft. from N line and 1451 ft. from E line of sec. 6

SE-1/4-NE-1/4 6 184 29E N.M.P.M.

Long Hills May San Mar

The elevation of the dirtier floor above sea level is 3613 ft.

DETAILS OF WORK

State nature of and expected depths of observations, logs, samples, and other data to be obtained, including logs, samples, and other data to be obtained.

Filled hole with mud from 365 feet to bottom 3121 feet and 15 sacks of cement from 315 feet to 365 feet. Mud from 40 feet to 315 feet cement from surface to 40 feet.

Recovered 162 feet of 8 1/8 pipe.

Finished plugging well May 18 1947.

RECEIVED

MAR 12 1964

D. C. DAVIS
ARTERIAL OFFICE

I understand that this plan of work must receive approval in writing by the Geological Survey before operations may be commenced.

Company S. S. Rogers

Address Box 151

Antonia Bay Hill

Tel. Drilling Co.