

UN ~~1062~~ COPY
DEPARTMENT OF THE INTERIOR
GEOLOGICAL SURVEY

SUBMIT IN TRIPL
(Other Instructions
verse side)

FE
re

Copy to DT
Form approved.
Budget Bureau No. 42-R1424.

5. LEASE DESIGNATION AND SERIAL NO.

LC-062072

6. IF INDIAN, ALLOTTEE OR TRIBE NAME

SUNDRY NOTICES AND REPORTS ON WELLS

(Do not use this form for proposals to drill or to deepen or plug back to a different reservoir.
Use "APPLICATION FOR PERMIT—" for such proposals.)

1.

OIL WELL ☒ GAS WELL ☐ OTHER

7. UNIT AGREEMENT NAME

West Loco Hills Grb #4 Sd Ut.

2. NAME OF OPERATOR

NEWMONT OIL COMPANY ✓

8. FARM OR LEASE NAME

TRACT 17

3. ADDRESS OF OPERATOR

P.O. Box 1305, Artesia, New Mexico 88210

9. WELL NO.

9

4. LOCATION OF WELL (Report location clearly and in accordance with any State requirements.
See also space 17 below.)

At surface

2310' FNL & 1650' FEL of Section 10

10. FIELD AND POOL, OR WILDCAT

Loco Hills (Q.G.SA)

11. SEC., T., R., M., OR BLK. AND
SURVEY OR AREA

Sec 10-T18S-R29E NMPM

14. PERMIT NO.

15. ELEVATIONS (Show whether DF, RT, GR, etc.)

3479' GLM

12. COUNTY OR PARISH

Eddy

13. STATE

New Mexico

16.

Check Appropriate Box To Indicate Nature of Notice, Report, or Other Data

NOTICE OF INTENTION TO:

SUBSEQUENT REPORT OF:

TEST WATER SHUT-OFF ☐

PULL OR ALTER CASING ☐

WATER SHUT-OFF ☐

REPAIRING WELL ☐

FRACTURE TREAT ☐

MULTIPLE COMPLETE ☐

FRACTURE TREATMENT ☐

ALTERING CASING ☐

SHOOT OR ACIDIZE ☐

ABANDON* ☐

SHOOTING OR ACIDIZING ☐

ABANDONMENT* ☐

REPAIR WELL ☐

CHANGE PLANS ☐

(Other) ☐

(NOTE: Report results of multiple completion on Well
Completion or Recompletion Report and Log form.)

(Other) Locate Water Source XXX

17. DESCRIBE PROPOSED OR COMPLETED OPERATIONS (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work. If well is directionally drilled, give subsurface locations and measured and true vertical depths for all markers and zones pertinent to this work.)*

5-8-78 -- A water leak has developed from the casing head. We have shut this well in and the water is draining into the existing pit from which it will be hauled back to the injection plant. We request permission to continue this operation until the water source is located. The District Engineer will be notified of our plans before the leak is repaired.

RECEIVED
MAY 9 1978
U.S. GEOLOGICAL SURVEY
ARTESIA, NEW MEXICO

18. I hereby certify that the foregoing is true and correct.

SIGNED

Ernest M. Monajil

TITLE

Office Manager.

DATE

5/8/78

(This space for Federal or State office use)

APPROVED BY

Lee D. Lara

TITLE

ACTING DISTRICT ENGINEER

DATE

MAY 12 1978

CONDITIONS OF APPROVAL, IF ANY:

Subject to the approval from the NMPS.

*See Instructions on Reverse Side