

UNITED STATES
DEPARTMENT OF THE INTERIOR
GEOLOGICAL SURVEY

SUBMIT IN TRIPL
(Other instructions
verse side)

Form approved.
Budget Bureau No. 42-R1424.

5. LEASE DESIGNATION AND SERIAL NO.

NM-02428

6. IF INDIAN, ALLOTTEE OR TRIBE NAME

7. UNIT AGREEMENT NAME

West Loco Hills Grb #4 Sd Ut.

8. FARM OR LEASE NAME

Tract 20

9. WELL NO.

1

10. FIELD AND POOL, OR WILDCAT

Loco Hills (Q.G.SA)

11. SEC., T., R., M., OR BLK. AND
SURVEY OR AREA

Sec 10-T18S-R29E NMPM

12. COUNTY OR PARISH

Eddy

13. STATE

New Mexico

1.

OIL ☐ GAS ☐ OTHER ☒ WIW

2. NAME OF OPERATOR

NEWMONT OIL COMPANY

3. ADDRESS OF OPERATOR

P.O. Box 1305, Artesia, New Mexico 88210

4. LOCATION OF WELL (Report location clearly and in accordance with any State requirements.)

See also space 17 below.
At surface

990' Fnl & 330' Fwl Of Section 10

14. PERMIT NO.

15. ELEVATIONS (Show whether DF, RT, GR, etc.)

3515' GLM

16.

Check Appropriate Box To Indicate Nature of Notice, Report, or Other Data

NOTICE OF INTENTION TO:

TEST WATER SHUT-OFF

PULL OR ALTER CASING

FRACTURE TREAT

MULTIPLE COMPLETE

SHOOT OR ACIDIZE

ABANDON*

REPAIR WELL

CHANGE PLANS

(Other)

Locate Water Source.

XXX

SUBSEQUENT REPORT OF:

WATER SHUT-OFF

REPAIRING WELL

FRACTURE TREATMENT

ALTERING CASING

SHOOTING OR ACIDIZING

ABANDONMENT*

(Other)

(NOTE: Report results of multiple completion on Well
Completion or Recompletion Report and Log form.)

17. DESCRIBE PROPOSED OR COMPLETED OPERATIONS (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work. If well is directionally drilled, give subsurface locations and measured and true vertical depths for all markers and zones pertinent to this work.)*

10-4-78 -- A water leak has developed from the casing head. A 7" Totem Tension packer is set on 2 3/8" OD tubing @ 2114" GLM in the 7" casing. The well is shut-in and has no pressure on the tubing. We request permission to monitor and test this well until the leak is located. The District Engineer will be notified of our plans before the leak is repaired.

A pit was dug to contain the water from this leak and we request permission to maintain this pit in a fenced manner with the water to be hauled to the injection plant.

RECEIVED
OCT 5 1978
U.S. GEOLOGICAL SURVEY
ARTESIA, NEW MEXICO

18. I hereby certify that the foregoing is true and correct

SIGNED

TITLE

Office Manager

DATE

10-4-78

(This space for Federal or State office use)

APPROVED BY

TITLE

ACTING DISTRICT ENGINEER

DATE

OCT - 6 1978

CONDITIONS OF APPROVAL, IF ANY: