

N. M. O. C. E. COPY
UNITED STATES
DEPARTMENT OF THE INTERIOR
GEOLOGICAL SURVEY
SUBMIT IN TRIPL
(Other instructions
verse side)Form approved.
Budget Bureau No. 42-R1424.

5. LEASE DESIGNATION AND SERIAL NO.

NM-02428

6. IF INDIAN, ALLOTTEE OR TRIBE NAME

SUNDRY NOTICES AND REPORTS ON WELLS

(Do not use this form for proposals to drill or to deepen or plug back to a different reservoir.
Use "APPLICATION FOR PERMIT—" for such proposals.)1. OIL ☐ GAS ☐ OTHER ☒ WIW
2. NAME OF OPERATOR
NEWMONT OIL COMPANY
3. ADDRESS OF OPERATOR
P.O. Box 1305, Artesia, New Mexico 882104. LOCATION OF WELL (Report location clearly and in accordance with any State requirements.
See also space 17 below.)
At surface

990' Fnl & 330' Fwl Of Section 10

14. PERMIT NO.
15. ELEVATIONS (Show whether DF, RT, GR, etc.)
3515' GLM

7. UNIT AGREEMENT NAME

West Loco Hills Grb #4 Sd Ut.

8. FARM OR LEASE NAME

Tract 20

9. WELL NO.

1

10. FIELD AND POOL, OR WILDCAT

Loco Hills (Q.G.SA)

11. SEC., T., R., M., OR BLK. AND
SURVEY OR AREA

Sec 10-T18S-R29E NMPM

12. COUNTY OR PARISH

Eddy

13. STATE

New Mexico

16. Check Appropriate Box To Indicate Nature of Notice, Report, or Other Data

NOTICE OF INTENTION TO:

SUBSEQUENT REPORT OF:

TEST WATER SHUT-OFF ☐ PULL OR ALTER CASING ☐
FRACTURE TREAT ☐ MULTIPLE COMPLETION ☐
SHOOT OR ACIDIZE ☐ ABANDON* ☐
REPAIR WELL ☐ CHANGE PLANS ☐
(Other) Locate Water Source. XXXWATER SHUT-OFF ☐ REPAIRING WELL ☐
FRACTURE TREATMENT ☐ ALTERING CASING ☐
SHOOTING OR ACIDIZING ☐ ABANDONMENT* ☐
(Other) _____
(NOTE: Report results of multiple completion on Well
Completion or Recompletion Report and Log form.)

17. DESCRIBE PROPOSED OR COMPLETED OPERATIONS (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work. If well is directionally drilled, give subsurface locations and measured and true vertical depths for all markers and zones pertinent to this work.) *

10-4-78 -- A water leak has developed from the casing head. A 7" Totem Tension packer is set on 2 3/8" OD tubing @ 2114" GLM in the 7" casing. The well is shut-in and has no pressure on the tubing. We request permission to monitor and test this well until the leak is located. The District Engineer will be notified of our plans before the leak is repaired.

A pit was dug to contain the water from this leak and we request permission to maintain this pit in a fenced manner with the water to be hauled to the injection plant.

RECEIVED

OCT 5 1978

U.S. GEOLOGICAL SURVEY
ARTESIA, NEW MEXICO

18. I hereby certify that the foregoing is true and correct

SIGNED Ernest J. McHenry TITLE Office Manager DATE 10-4-78

(This space for Federal or State office use)

APPROVED BY John J. Lara TITLE ACTING DISTRICT ENGINEER DATE OCT - 6 1978
CONDITIONS OF APPROVAL, IF ANY: