

(SUBMIT IN TRIPLICATE)

UNITED STATES DEPARTMENT OF THE INTERIOR GEOLOGICAL SURVEY

Budget Sureau No. 42 Rate.4

Land Citics Las Cruces

. N. LC 055430

Lucia Brooks

SEP 1 7 1989

## SUNDRY NOTICES AND REPORTS ON WELLS S. C. C.

NOTICE OF INTENTION TO DRILL

NOTICE OF INTENTION TO CHANGE PLANS

NOTICE OF INTENTION TO TEST WATER SHUT-OFF

NOTICE OF INTENTION TO RE-DRILL OR REPAIR WELL

NOTICE OF INTENTION TO SHOOT OR ACIDIZE

NOTICE OF INTENTION TO PULL OR ALTER CASING

NOTICE OF INTENTION TO ABANDON WELL

SUBSEQUENT REPORT OF WATER SHUT-OFF

SUBSECULENT REPORT OF SHOOTING OR ACIDIZING

E SUBSEQUENT REPORT OF ALTERING CASING

SUBSEQUENT REPORT OF RE-DRILLING OR REPAIR

SUBSEQUENT REPORT OF ABANDONMENT

Artesia, New Mexico

September 7,

is located

660 ft. from N line and 1980 ft. from E line of sec. 13

Mai Mai Sec. 13

M. M. F. H. (Maridian)

Loco Milla

Eddy

The elevation of the derrick floor above sea level is

ft.

## DETAILS OF WORK

Set 10 sack cement plug at 3200 feet. Sroke off and pulled 2300 test of I" casing. Hilled hole with mud to Isid and rem 10 sack coment plug in  $7^{T}$  casing stub. Filled hole with mud to 440 feet. wan 15 saus coment plug at bottom of and extending up into 8% casing. Filled hole with and to surface and set regulation marker in 10 sack cement plug.

Well plugged and abandoned in June, 1947.

DIKON & YATES UIL COMPANY Company

Address

323 Carper Building,

Artesia, New Mexico.

Title

7 ~