

(SUBMIT IN TRIPLICATE)

UNITED STATES
DEPARTMENT OF THE INTERIOR
GEOLOGICAL SURVEYLand Office Las Cruces
Lease No. 058126
Unit H

RECEIVED

SEP 17 1962

SUNDRY NOTICES AND REPORTS ON WELLS, C. C.

NOTICE OF INTENTION TO DRILL	SUBSEQUENT REPORT OF WATER SHUT-OFF
NOTICE OF INTENTION TO CHANGE PLANS	SUBSEQUENT REPORT OF SHOOTING OR ACIDIZING
NOTICE OF INTENTION TO TEST WATER SHUT-OFF	SUBSEQUENT REPORT OF ALTERING CASING
NOTICE OF INTENTION TO RE-DRILL OR REPAIR WELL	SUBSEQUENT REPORT OF RE-DRILLING OR REPAIR
NOTICE OF INTENTION TO SHOOT OR ACIDIZE	SUBSEQUENT REPORT OF ABANDONMENT
NOTICE OF INTENTION TO PULL OR ALTER CASING	SUPPLEMENTARY WELL HISTORY
NOTICE OF INTENTION TO ABANDON WELL	

(INDICATE ABOVE BY CHECK MARK NATURE OF REPORT, NOTICE, OR OTHER DATA)

August 28, 1962

Travis
Well No. 9 is located 1900 ft. from [N] line and 660 ft. from [E] line of sec. 19
SE/4 NE/4 19 18S 29E NMPL
($\frac{1}{4}$ Sec. and Sec. No.) (Twp.) (Range) (Meridian)
Loco Hills Eddy New Mexico
(Field) (County or Subdivision) (State or Territory)

The elevation of the derrick floor above sea level is _____ ft.

DETAILS OF WORK

(State names of and expected depths to objective sands; show sizes, weights, and lengths of proposed casings; indicate mudding jobs, cementing points, and all other important proposed work)

We knocked off 5-1/2" pipe at 1500'. Ran 2400' tubing.

We circulated hole w/gel. Set cement plugs as follows:

100' plug - 16 sks out from 2400-2300; 100' plug - 33 sks out from 1450-1350;

100' plug - 33 sks out from 860-760; 100' plug - 33 sks out from 450-350;

25' plug at surface. Placed dry hole marker and abandoned.

I understand that this plan of work must receive approval in writing by the Geological Survey before operations may be commenced.

Company Harvey E. YatesAddress 320 Carper Bldg.Artesia, New MexicoBy [Signature]Title Bookkeeper