Form Approved.

5. LEASE

Budget Bureau No. 42-R1424

NM OIL COMS. COMMISS_A Dec. 1997 awer DD

Antocia, 771 MINITED STATES

DEPARTMENT OF THE INTERIOR **GEOLOGICAL SURVEY**

DEPARTMENT OF THE INTERIOR GEOLOGICAL SURVEY	NM-0925 6. IF INDIAN, ALLOTTEE OR TRIBE NAME	
SUNDRY NOTICES AND REPORTS ON WELLS (Do not use this form for proposals to drill or to deepen or plug back to a different reservoir. Use Form 9–331–C for such proposals.)	7. UNIT AGREEMENT NAME South Loco Hills Unit 8. FARM OR LEASE NAME	
1. oil gas other	South Loco Hills Unit 9. WELL NO.	RECEIVED BY
2. NAME OF OPERATOR Yates Drilling Company	10 10. FIELD OR WILDCAT NAME	JUN 111984
3. ADDRESS OF OPERATOR 207 South 4th St., Artesia, N.M. 88210	Loco Hills-Q-G-SA O. C. D. 11. SEC., T., R., M., OR BLK. AND SURVER TESIA, CONTES	
4. LOCATION OF WELL (REPORT LOCATION CLEARLY. See space 17 below.) AT SURFACE: 1980' FNL & 1980' FWL AT TOP PROD. INTERVAL:	AREA Sec. 20-T18S-R29E 12. COUNTY OR PARISH 13. STATE	
AT TOTAL DEPTH: 16. CHECK APPROPRIATE BOX TO INDICATE NATURE OF NOTICE, REPORT, OR OTHER DATA	14. API NO.	.M. AND WD)
REQUEST FOR APPROVAL TO: SUBSEQUENT REPORT OF	3570' KB	
TEST WATER SHUT-OFF FRACTURE TREAT SHOOT OR ACIDIZE REPAIR WELL PULL OR ALTER CASING MULTIPLE COMPLETE CHANGE ZONES ABANDON* (other) Put well back on production. 17. DESCRIBE PROPOSED OR COMPLETED OPERATIONS (Clearly state including estimated date of starting any proposed work. If well is d measured and true vertical depths for all markers and zones pertinent. This well was temp. abandon. We checked T.D. Ran Pump and 3/4 rod. Installed pumping equip	rectionally drilled, give subsurface locate to this work.)* and ran 2381.33 ft. 203	near dates, cations and
Subsurfees Cofety Value Many and Turn		
Subsurface Safety Valve: Manu. and Type 18. I hereby certify that the foregoing is true and correct	Set @	Ft.
SIGNED SIGNED TITLE Production Su	unary ion Anril 24	100/
		204
ACCEPTED FOR RECORDING Space for Federal or State offi APPROVED BY		

(alelan), NEW MEXICO