

UNITEL TATES
DEPARTMENT OF THE INTERIOR
GEOLOGICAL SURVEY

SUNDRY NOTICES AND REPORTS ON WELLS

(Do not use this form for proposals to drill or deepen or otherwise alter a different reservoir. Use Form 9-331-C for such proposals.)

RECEIVED

FEB 10 1983

O. C. D.

ARTESIA OFFICE

1. oil well ☐ gas well ☐ other ☐ PSA
2. NAME OF OPERATOR
Yates Drilling Co.
3. ADDRESS OF OPERATOR
207 S. 4th St., Artesia, NM 88210
4. LOCATION OF WELL (REPORT LOCATION CLEARLY. See space 17 below.)
AT SURFACE: 2310 FSL & 2310 FSL
AT TOP PROD. INTERVAL:
AT TOTAL DEPTH:

16. CHECK APPROPRIATE BOX TO INDICATE NATURE OF NOTICE, REPORT, OR OTHER DATA

REQUEST FOR APPROVAL TO: SUBSEQUENT REPORT OF:

TEST WATER SHUT-OFF
FRACTURE TREAT
SHOOT OR ACIDIZE
REPAIR WELL
PULL OR ALTER CASING
MULTIPLE COMPLETE
CHANGE ZONES
ABANDON*

(other) Replug well. O.C.D. Order No. R-7012

17. DESCRIBE PROPOSED OR COMPLETED OPERATIONS (Clearly state all pertinent details, and give pertinent dates including estimated date of starting any proposed work. If well is directionally drilled, give subsurface locations and measured and true vertical depths for all markers and zones pertinent to this work.)*

Replugged well as follows: Cleaned out to 2508'. Set 100 sx Class "C" cement plug at 2508'. Tagged plug at 2150'. Set 75 sx Class "C" w/3% CaCl cement plug at 840'. Tagged plug at 658'. Set 75 sx Class "C" w/3% CaCl cement plug at 418'. Tagged plug at 210'. Set 35 sx surface plug. Installed dry hole marker. Work started 10-14-82. Work completed 10-18-82.
Witnessed by Mr. Mike Williams, OCD, Artesia.

Subsurface Safety Valve: Model and Type

Set @ _____ Ft.

18. I hereby certify that the foregoing is true and correct

SIGNED _____ TITLE Engineering Secty DATE 10-18-82

(This space for Federal or State office use)

APPROVED BY
CONDITIONS OF APPROVAL, IF ANY

TITLE

DATE