


Form 9-581a
(Feb. 1951)



ARTESIA OFFICE COPY

(SUBMIT IN TRIPLICATE)

UNITED STATES
DEPARTMENT OF THE INTERIOR
GEOLOGICAL SURVEY

Budget Bureau 42-228.1
Approval expires 12-31-52

Land Office **Los Cruces**

Lease No. **N.M. 0924**

RECEIVED
JAN 24 1958

U. S. GEOLOGICAL SURVEY
ARTESIA, NEW MEXICO

SUNDRY NOTICES AND REPORTS ON WELLS

NOTICE OF INTENTION TO DRILL.....	SUBSEQUENT REPORT OF WATER SHUT-OFF.....
NOTICE OF INTENTION TO CHANGE PLANS.....	SUBSEQUENT REPORT OF SHOOTING OR ACIDIZING.....
NOTICE OF INTENTION TO TEST WATER SHUT-OFF.....	SUBSEQUENT REPORT OF ALTERING CASING.....
NOTICE OF INTENTION TO RE-DRILL OR REPAIR WELL.....	SUBSEQUENT REPORT OF RE-DRILLING OR REPAIR.....
NOTICE OF INTENTION TO SHOOT OR ACIDIZE.....	SUBSEQUENT REPORT OF ABANDONMENT.....
NOTICE OF INTENTION TO PULL OR ALTER CASING.....	SUPPLEMENTARY WELL HISTORY.....
NOTICE OF INTENTION TO ABANDON WELL.....	

(INDICATE ABOVE BY CHECK MARK NATURE OF REPORT, NOTICE, OR OTHER DATA)

Goodale January 13, 1958
Well No. 2 is located 330 ft. from (N) line and 2310/W ft. from (S) line of sec. 21
NE 1/4 Sec. 31 16 S 29 E
(1/4 Sec. and Sec. No.) (Twp.) (Range) (Meridian)
Palmito Eddy New Mexico
(Field) (County or Subdivision) (State or Territory)

The elevation of the derrick floor above sea level is 3444 ft.

DETAILS OF WORK

(State names of and expected depths to objective sands; show sizes, weights, and lengths of proposed casings; indicate mudding jobs, cementing points, and all other important proposed work)

The Hole was mudded up from 300 plugged back T.D. of 1955.
140' of the 300' of 8-5/8" casing was recovered.

Cement plugs of 5 sacks each were run at 1500', 790' and 300 and 5 sacks at the top of hole.

The regulation dry hole marker was erected.

I understand that this plan of work must receive approval in writing by the Geological Survey before operations may be commenced.

Company Hess Williams

Address Box 1448

Artesia, New Mexico

By John A. Subduth

Title Engineer