


Form 9-281a  
(Feb. 1961)

(SUBMIT IN TRIPLICATE)

UNITED STATES  
DEPARTMENT OF THE INTERIOR  
GEOLOGICAL SURVEY

Land Office \_\_\_\_\_

Lease No. **010907**Unit **A**

## SUNDRY NOTICES AND REPORTS ON WELLS

NOTICE OF INTENTION TO DRILL	SUBSEQUENT REPORT OF WATER SHUT-OFF	
NOTICE OF INTENTION TO CHANGE PLANS	SUBSEQUENT REPORT OF SHOOTING OR ACIDIZING	
NOTICE OF INTENTION TO TEST WATER SHUT-OFF	SUBSEQUENT REPORT OF ALTERING CASING	
NOTICE OF INTENTION TO RE-DRILL OR REPAIR WELL	SUBSEQUENT REPORT OF RE-DRILLING OR REPAIR	
NOTICE OF INTENTION TO SHOOT OR ACIDIZE	SUBSEQUENT REPORT OF ABANDONMENT	<b>X</b>
NOTICE OF INTENTION TO PULL OR ALTER CASING	SUPPLEMENTARY WELL HISTORY	
NOTICE OF INTENTION TO ABANDON WELL		

(INDICATE ABOVE BY CHECK MARK NATURE OF REPORT, NOTICE, OR OTHER DATA)

April 9, 1959

McKee-Taylor

Well No. **1** is located **660** ft. from **[N]** line and **660** ft. from **[E]** line of sec. **34****NE 34**  
(1/4 Sec. and Sec. No.)**18 S**  
(Twp.)**29 E**  
(Range)**U.M.P.**  
(Meridian)**Turkey Track**  
(Field)**Kady**  
(County or Subdivision)**New Mexico**  
(State or Territory)The elevation of the derrick floor above sea level is **3409** ft.

## DETAILS OF WORK

(State names of and expected depths to objective sands; show sizes, weights, and lengths of proposed casings; indicate mudding jobs, cementing points, and all other important proposed work)

332 ft of 8 5/8" pipe run and cemented with 20 sacks. The well was drilled to 2096 feet where water was encountered. There was no oil or gas encountered in this well in commercial quantities. Well was plugged as per your instructions as follows:

Hole was mudded to bottom of salt and a 10 sack cement plug installed. Hole was then mudded to bottom of 8 5/8" pipe and a 10 sack plug installed. Pipe was knucked off at 2 3/4 feet and a 10 sack plug installed. Hole was then mudded to near the surface and a regulation marker cemented in hole and location cleaned up.

I understand that this plan of work must receive approval in writing by the Geological Survey before operations may be commenced.

Company **Robert E. McKee General Contractor, Inc.**Address **210 Vermont Drive****Artesia, New Mexico**By *[Signature]*  
Manager of Oil Production

Title \_\_\_\_\_