



(SUBMIT IN TRIPLICATE)

UNITED STATES
DEPARTMENT OF THE INTERIOR
GEOLOGICAL SURVEY

Land Office _____

Lease No. NM 015068

Unit _____

RECEIVED
FEB 22 1961

D. C. D.
ARTESIA, OFFICE

SUNDRY NOTICES AND REPORTS ON WELLS

NOTICE OF INTENTION TO DRILL	SUBSEQUENT REPORT OF WATER SHUT-OFF	
NOTICE OF INTENTION TO CHANGE PLANS	SUBSEQUENT REPORT OF SHOOTING OR ACIDIZING	
NOTICE OF INTENTION TO TEST WATER SHUT-OFF	SUBSEQUENT REPORT OF ALTERING CASING	
NOTICE OF INTENTION TO RE-DRILL OR REPAIR WELL	SUBSEQUENT REPORT OF RE-DRILLING OR REPAIR	
NOTICE OF INTENTION TO SHOOT OR ACIDIZE	SUBSEQUENT REPORT OF ABANDONMENT	
NOTICE OF INTENTION TO PULL OR ALTER CASING	SUPPLEMENTARY WELL HISTORY	
NOTICE OF INTENTION TO ABANDON WELL	Results of Well Treatment	X

(INDICATE ABOVE BY CHECK MARK NATURE OF REPORT, NOTICE, OR OTHER DATA)

February 20, 1961

Well No. 1 is located 2310 ft. from N line and 1980 ft. from W line of sec. 34

SE/4 NW/4 T18S R29E N.M.P.M.
($\frac{1}{4}$ Sec. and Sec. No.) (Twp.) (Range) (Meridian)

Turkey Track Eddy County New Mexico
(Field) (County or Subdivision) (State or Territory)

The elevation of the derrick floor above sea level is _____ ft.

DETAILS OF WORK

(State names of and expected depths to objective sands; show sizes, weights, and lengths of proposed casings; indicate mudding jobs, cementing points, and all other important proposed work)

Results of treating open hole from 2090 - 2106 with 420 barrels of lease crude and 6,000 pounds of 8-12 mesh sand.

(2-1-61) Before treatment well made: 3.5 bbl. of oil, 0 bbl. water

(2-11-61) After treatment well made: 8.3 bbl. of oil, 0 bbl. water

I understand that this plan of work must receive approval in writing by the Geological Survey before operations may be commenced.

Company Stanton Oil Co., Agent for R. E. McKee, Gen. Contr.

Address 408 Wilkinson Foster Building

Midland, Texas

By Original Signed by Wm. E. Fickert

Title Agent

