


APPROVED

(SUBMIT IN TRIPLICATE)

UNITED STATES
DEPARTMENT OF THE INTERIOR
GEOLOGICAL SURVEYLand Office ~~ARTESIA~~
Lease No. **LC 070251-A**
Unit **1**

RECEIVED

OCT 8 1962

SUNDRY NOTICES AND REPORTS ON WELLS

NOTICE OF INTENTION TO DRILL.....	SUBSEQUENT REPORT OF WATER SHUT-OFF.....	D. E. D. ARTESIA, OFFICE
NOTICE OF INTENTION TO CHANGE PLANS.....	SUBSEQUENT REPORT OF SHOOTING OR ACIDIZING.....	
NOTICE OF INTENTION TO TEST WATER SHUT-OFF.....	SUBSEQUENT REPORT OF ALTERING CASING.....	
NOTICE OF INTENTION TO RE-DRILL OR REPAIR WELL.....	SUBSEQUENT REPORT OF RE-DRILLING OR REPAIR.....	
NOTICE OF INTENTION TO SHOOT OR ACIDIZE.....	SUBSEQUENT REPORT OF ABANDONMENT.....	
NOTICE OF INTENTION TO PULL OR ALTER CASING.....	SUPPLEMENTARY WELL HISTORY.....	
NOTICE OF INTENTION TO ABANDON T.A.	Subsequent Report to T.A.	

(INDICATE ABOVE BY CHECK MARK NATURE OF REPORT, NOTICE, OR OTHER DATA)

October 3, 1962

Well No. **1** is located **1900** ft. from **N** line and **660** ft. from **W** line of sec. **29**
NM/4 SW/4 29 18E 29E M.M.P.M.
(1/4 Sec. and Sec. No.) (Twp.) (Range) (Meridian)
Undesignated Edwy New Mexico
(Field) (County or Subdivision) (State or Territory)

The elevation of the derrick floor above sea level is **3470** ft.

DETAILS OF WORK

(State names of and expected depths to objective sands; show sizes, weights, and lengths of proposed casings; indicate mudding jobs, cementing points, and all other important proposed work)

6-7-62

T.D. 395'. Svedged and cased 7" to T.A.
T.A. 6-7-62.RECEIVED
OCT 4 1962
U. S. GEOLOGICAL SURVEY
ALBUQUERQUE, NEW MEXICO

I understand that this plan of work must receive approval in writing by the Geological Survey before operations may be commenced.

Company **Yates Petroleum Corporation**Address **309 Casper Building****Artesia, New Mexico**

By

Title

Geologist