

(SUBMIT IN TRIPLICATE)

UNITED STATES
DEPARTMENT OF THE INTERIOR
GEOLOGICAL SURVEY

Land Office

Lease No. **MM - 021095**

Unit

RECEIVED

AUG 28 1953

SUNDRY NOTICES AND REPORTS ON WELLS

ARTESIA, OFFICE	
NOTICE OF INTENTION TO DRILL	SUBSEQUENT REPORT OF WATER SHUT-OFF
NOTICE OF INTENTION TO CHANGE PLANS	SUBSEQUENT REPORT OF SHOOTING OR ACIDIZING
NOTICE OF INTENTION TO TEST WATER SHUT-OFF	SUBSEQUENT REPORT OF ALTERING CASING
NOTICE OF INTENTION TO RE-DRILL OR REPAIR WELL	SUBSEQUENT REPORT OF RE-DRILLING OR REPAIR
NOTICE OF INTENTION TO SHOOT OR ACIDIZE	SUBSEQUENT REPORT OF ABANDONMENT
NOTICE OF INTENTION TO PULL OR ALTER CASING	SUPPLEMENTARY WELL HISTORY
NOTICE OF INTENTION TO ABANDON WELL	

Frac **X**

(INDICATE ABOVE BY CHECK MARK NATURE OF REPORT, NOTICE, OR OTHER DATA)

June 15, 1943

Well No. **Notes A 10** located **330** ft. from **NU** line and **990** ft. from **EX** line of sec. **6****SW/4 SW/4 Sec. 6**
(1/4 Sec. and Sec. No.)**18-5**
(Twp.)**30-E**
(Range)**MMPM**
(Meridian)**Loco Hills**
(Field)**Eddy**
(County or Subdivision)**New Mexico**
(State or Territory)

The elevation of the derrick floor above sea level is _____ ft.

DETAILS OF WORK

(State names of and expected depths to objective sands; show sizes, weights, and lengths of proposed casings; indicate mudding jobs, cementing points, and all other important proposed work)

We propose to sandrill 2815-19, run packer and fracture with 15,000 gallons lease oil and 15,000# sand. Well will then be put back on production.

RECEIVED
AUG 28 1953
U. S. GEOLOGICAL SURVEY
ARTESIA, NEW MEXICO

I understand that this plan of work must receive approval in writing by the Geological Survey before operations may be commenced.

Company **HELMONT OIL COMPANY**Address **Rowley Building****Artesia, New Mexico**ORIGINAL SIGNED BY
H. J. LEDBETTER

By

Title **Superintendent**