

(SUBMIT IN TRIPLICATE)

UNITED STATES
DEPARTMENT OF THE INTERIOR
GEOLOGICAL SURVEY

Land Office _____

Lease No. **MM** - **021095**

Unit **2m**

AUG 27 1963

ARTESIA, OFFICE

SUNDRY NOTICES AND REPORTS ON WELLS

NOTICE OF INTENTION TO DRILL	SUBSEQUENT REPORT OF WATER SHUT-OFF
NOTICE OF INTENTION TO CHANGE PLANS	SUBSEQUENT REPORT OF SHOOTING OR ACIDIZING
NOTICE OF INTENTION TO TEST WATER SHUT-OFF	SUBSEQUENT REPORT OF ALTERING CASING
NOTICE OF INTENTION TO RE-DRILL OR REPAIR WELL	SUBSEQUENT REPORT OF RE-DRILLING OR REPAIR
NOTICE OF INTENTION TO SHOOT OR ACIDIZE	SUBSEQUENT REPORT OF ABANDONMENT
NOTICE OF INTENTION TO PULL OR ALTER CASING	SUPPLEMENTARY WELL HISTORY
NOTICE OF INTENTION TO ABANDON WELL	

(INDICATE ABOVE BY CHECK MARK NATURE OF REPORT, NOTICE, OR OTHER DATA)

August 27, 1963

Well **Novates A 10** is located **330** ft. from **(N)** line and **990** ft. from **(E)** line of sec. **6**

SW/4 SW/4 Sec. 6 (1/4 Sec. and Sec. No.) **13-S** (Twp.) **30-E** (Range) **MM** (Meridian)
Loco Mills (Field) **Eddy** (County or Subdivision) **New Mexico** (State or Territory)

The elevation of the derrick floor above sea level is _____ ft.

DETAILS OF WORK

(State names of and expected depths to objective sands; show sizes, weights, and lengths of proposed casings; indicate mudding jobs, cementing points, and all other important proposed work)

On 6-28-63 sandrilled 2815-19 for 20 minutes. We then fraced with 15,000 gallons lease oil, 14,600# sand, 275# Adomite and 30 gallons MWI. After recovering load oil well made 132 oil and 14 water in 24 hours.

I understand that this plan of work must receive approval in writing by the Geological Survey before operations may be commenced.

Company **MEMMONT OIL COMPANY**

Address **Rowley Building**

Artesia, New Mexico

ORIGINAL SIGNED BY

By **H. J. LEDBETTER**

Title **Superintendent**