

GEOLOGICAL SURVEY  
DEPARTMENT OF THE INTERIOR  
UNITED STATES

(Nov. 1936)  
Indian Agency .....

(SUBMIT IN TRIPLICATE)

U. S. Land Office .....

Allottee .....

UNITED STATES  
DEPARTMENT OF THE INTERIOR  
GEOLOGICAL SURVEY

Lease or permit No. ....

Lease No. ....

## SUNDRY NOTICES AND REPORTS ON WELLS

NOTICE OF INTENTION TO DRILL .....	SUBSEQUENT REPORT OF WATER SHUT-OFF .....	XX
NOTICE OF INTENTION TO CHANGE PLANS .....	SUBSEQUENT REPORT OF SHOOTING OR ACIDIZING .....	
NOTICE OF INTENTION TO TEST WATER SHUT-OFF .....	SUBSEQUENT REPORT OF ALTERING CASING .....	
NOTICE OF INTENTION TO RE-DRILL OR REPAIR WELL .....	SUBSEQUENT REPORT OF REDRILLING OR REPAIR .....	
NOTICE OF INTENTION TO SHOOT OR ACIDIZE .....	SUBSEQUENT REPORT OF ABANDONMENT .....	
NOTICE OF INTENTION TO PULL OR ALTER CASING .....	SUPPLEMENTARY WELL HISTORY .....	
NOTICE OF INTENTION TO ABANDON WELL .....		

(INDICATE ABOVE BY CHECK MARK NATURE OF REPORT, NOTICE, OR OTHER DATA)

9/26/39, 19...

Well No. 1 is located 250 ft. from N line and 350 ft. from E line of sec. 7

18 S 70 E N 100 W  
(Twp.) (Range) (Meridian)  
1000 Hills Eddy New Mexico  
(Field) (County or Subdivision) (State or Territory)

The elevation of the derrick floor above sea level is ..... ft.

### DETAILS OF WORK

(State names of and expected depths to objective sands; show sizes, weights, and lengths of proposed casings; indicate mudding jobs, cementing points, and all other important proposed work)

Set 2671' of 7" OP 20# Seamless casing 70' in the line and cemented with 100 Sacks of cement and 5 tons of mud using Halliburton equipment.

On September 25th. 1939, after waiting 72 hours for cement to set, drilled plug and tested with a 4 hour bailing test and found we had a complete water shut off.

I understand that this plan of work must receive approval in writing by the Geological Survey before operations may be commenced.

Company Franklin Petroleum Corporation

Address Box # 228, Smith, New Mexico.

By [Signature]

Title Sec. 2, Smith.