

(SUBMIT IN TRIPLICATE)

Land Office Las Cruces

Lease No. 047269-A

Unit Sanfield 4A

APPROVED

ACTING DISTRICT ENGINEER

UNITED STATES
DEPARTMENT OF THE INTERIOR
GEOLOGICAL SURVEY

SUNDRY NOTICES AND REPORTS ON WELLS

NOTICE OF INTENTION TO DRILL	SUBSEQUENT REPORT OF WATER SHUT-OFF	X
NOTICE OF INTENTION TO CHANGE PLANS	SUBSEQUENT REPORT OF SHOOTING OR ACIDIZING	
NOTICE OF INTENTION TO TEST WATER SHUT-OFF	SUBSEQUENT REPORT OF ALTERING CASING	
NOTICE OF INTENTION TO RE-DRILL OR REPAIR WELL	SUBSEQUENT REPORT OF REDRILLING OR REPAIR	
NOTICE OF INTENTION TO SHOOT OR ACIDIZE	SUBSEQUENT REPORT OF ABANDONMENT	
NOTICE OF INTENTION TO PULL OR ALTER CASING	SUPPLEMENTARY WELL HISTORY	
NOTICE OF INTENTION TO ABANDON WELL		

(INDICATE ABOVE BY CHECK MARK NATURE OF REPORT, NOTICE, OR OTHER DATA)

Sanfield
92426 In 1 Wells
Well No. 4 is located 660 ft. from [N] line and 660 ft. from [E] line of sec. 7
7 (Sec. and Sec. No.) 188 (Twp.) 305 (Range) NMPM (Meridian)
Leona Hills (Field) El Paso (County or Subdivision) New Mexico (State or Territory)

The elevation of the derrick floor above sea level is _____ ft.

DETAILS OF WORK

(State names of and expected depths to objective sands; show sizes, weights, and lengths of proposed casings; indicate mudding jobs, cementing points, and all other important proposed work)

On January 14, 1944 ran 402 feet used 8" lapweld casing and cemented with 50 sacks of cement preceded by mud circulated to the top using Halliburton Oil Well Cementing equipment.

On January 18, 1944 after waiting 72 hours for cement to set bailed hole, drilled plug and after 4 hours bailing test determined water shut-off f.

RECEIVED

GEOLOGICAL SURVEY

RECEIVED

FEB 10 1944

I understand that this plan of work must receive approval in writing by the Geological Survey before operations may be commenced.

Company Franklin Petroleum Corp.

Address Production Engineering

215 Ward Building

Artesia, New Mexico

By

Chuck Aston
Title Geologist

Noted
J. A. Barnett