Form 9-881 a (Feb. 1951)

(SUBMIT IN TRIPLICATE)

## UNITED STATES DEPARTMENT OF THE INTERIOR **GEOLOGICAL SURVEY**

Budget B Form App	ureau No. 42-R358.4.	
Land Office	LC	$\sqrt{\gamma}$
Lease No	047269 (A)	9

(State or Territory)

WFX # 157

	HECK MARK NATURE OF REPORT, NOTICE, OR OTHER DATA)  JENUSTY 29
WLHU Well No. 7 1-4 is located 660 SW/4 SW/4 Sec. 7 18-8	ft. from \\\ \\ \\ \\ \\ \\ \\ \\ \\ \\ \\ \\ \

The elevation of the derrick floor above sea level is ......ft.

Redy

## DETAILS OF WORK

(County or Subdivision)

(State names of and expected depths to objective sands; show sizes, weights, and lengths of proposed casings; indicate mudding jobs, cementing points, and all other important proposed work)

1/5/44

fulled reds and tubing.

1/7/64

all on intertion.

RECELLIPSER

C. Crick

C. Crick

I understand that this plan of work must receive approval in writing by the Geological Survey before operations may be commenced.				
Company .	Newmont Gil Company	graph of the commenced.		
Address	Rowley building			
	Artesia, her hexico	ORIGINAL SIGNED BY H. J. LEDBETTER		
		Title District Superintendent		