

DEPARTMENT OF THE INTERIOR
GEOLOGICAL SURVEY

Form approved.
Budget Bureau No. 42-R1424.
Form approved.
Budget Bureau No. 42-R1424.

5. LEASE DESIGNATION AND SERIAL NO.

LC 063621-A

SUNDRY NOTICES AND REPORTS ON WELLS

(Do not use this form for proposals to drill or to deepen or plug back to a different reservoir.
Use "APPLICATION FOR PERMIT—" for such proposals.)

RECEIVED

1. OIL WELL ☐ GAS WELL ☒ OTHER DRY HOLE

JUN 15 1976

2. NAME OF OPERATOR
FRANKLIN, ASTON & FAIR, LTD.

3. ADDRESS OF OPERATOR
P. O. BOX 1090, ROSWELL, NEW MEXICO 88201

O.C.C.
ARTESIA, OFFICE

4. LOCATION OF WELL (Report location clearly and in accordance with any State requirements.
See also space 17 below.)
At surface

1650' FNL - 1650' FEL

14. PERMIT NO.

15. ELEVATIONS (Show whether DF, RT, GR, etc.)

3467' DF

11. SEC., T., R., M., OR BLK. AND SURVEY OR AREA
SEC. 17 - 18S - 30E

12. COUNTY OR PARISH 13. STATE

EDDY COUNTY NEW MEXICO

16.

Check Appropriate Box To Indicate Nature of Notice, Report, or Other Data

NOTICE OF INTENTION TO:

TEST WATER SHUT-OFF

FRACTURE TREAT

SHOOT OR ACIDIZE

REPAIR WELL

(Other)

PULL OR ALTER CASING

MULTIPLE COMPLETE

ABANDON*

CHANGE PLANS

SUBSEQUENT REPORT OF:

WATER SHUT-OFF

FRACTURE TREATMENT

SHOOTING OR ACIDIZING

(Other)

REPAIRING WELL

ALTERING CASING

ABANDONMENT*

(NOTE: Report results of multiple completion on Well Completion or Recompletion Report and Log form.)

17. DESCRIBE PROPOSED OR COMPLETED OPERATIONS (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work. If well is directionally drilled, give subsurface locations and measured and true vertical depths for all markers and zones pertinent to this work.) *

On March 20, 1976, this well was plugged and abandoned as follows:

Two-inch (2") tubing was run to bottom 2907 feet and the hole circulated with heavy mud:

25 sack cement plug 2907 to 2807 feet across Loco Hills;
25 sack cement plug 1250 to 1150 feet at base of Salt;
35 sack cement plug 550 to 450 feet in and out base of 8 5/8 inch casing;
10 sack cement plug and marker at surface.

The cementing was done by Halliburton, and heavy mud is between all plugs.

RECEIVED
APR - 5 1976
U.S. GEOLOGICAL SURVEY
ARTESIA, NEW MEXICO

18. I hereby certify that the foregoing is true and correct

SIGNED *Grant W. Smith*

TITLE Geologist

DATE April 2, 1976

(This space for Federal or State office use)

APPROVED BY
CONDITIONS OF APPROVAL IF ANY:

TITLE

DATE

ACTING DISTRICT ENGINEER

*See Instructions on Reverse Side