



(SUBMIT IN TRIPLICATE)

UNITED STATES
DEPARTMENT OF THE INTERIOR
GEOLOGICAL SURVEY

Land Office _____
Lease No. **LC 063621**
Unit **1**

SUNDRY NOTICES AND REPORTS ON WELLS

NOTICE OF INTENTION TO DRILL.....	SUBSEQUENT REPORT OF WATER SHUT-OFF.....	
NOTICE OF INTENTION TO CHANGE PLANS.....	SUBSEQUENT REPORT OF SHOOTING OR ACIDIZING.....	
NOTICE OF INTENTION TO TEST WATER SHUT-OFF.....	SUBSEQUENT REPORT OF ALTERING CASING.....	
NOTICE OF INTENTION TO RE-DRILL OR REPAIR WELL.....	SUBSEQUENT REPORT OF RE-DRILLING OR REPAIR.....	
NOTICE OF INTENTION TO SHOOT OR ACIDIZE.....	SUBSEQUENT REPORT OF ABANDONMENT.....	<input checked="" type="checkbox"/>
NOTICE OF INTENTION TO PULL OR ALTER CASING.....	SUPPLEMENTARY WELL HISTORY.....	
NOTICE OF INTENTION TO ABANDON WELL.....		

(INDICATE ABOVE BY CHECK MARK NATURE OF REPORT, NOTICE, OR OTHER DATA)

10/3, 19**61**

Well No. **1 So. Union** is located **2310** ft. from **N** line and **330** ft. from **W** line of sec. **17**

SMM 17 **185** **30E** **NMPS**
($\frac{1}{4}$ Sec. and Sec. No.) (Twp.) (Range) (Meridian)

(Field) (County or Subdivision) (State or Territory)

The elevation of the derrick floor above sea level is **3496** ft.

DETAILS OF WORK

(State names of and expected depths to objective sands; show sizes, weights, and lengths of proposed casings; indicate mudding jobs, cementing points, and all other important proposed work)

As per our notice of intention to plug, dated 10/3/61, all plugs were set as intended, with exception of top plug. This was set and baler was run and the top of plug was at 388 to 485 and to surface, set pipe marker in 10 sacks cement.

ILLEGIBLE

RECEIVED

OCT 9 1961

U. S. GEOLOGICAL SURVEY

ARTESIA, NEW MEXICO

I understand that this plan of work must receive approval in writing by the Geological Survey before operation.

Company **A. J. Smith Drilg. Co.**

Address **Box 631**

Artesia, New Mexico

By *Manning Sanders*
Title **Asst**