

FEB 24 1948

ARTESIA OFFICE COPY

Budget Bureau No. 43-2388.1
Approval expires 11-30-48.

APPROVED

Joe Smith
DISTRICT ENGINEER

(SUBMIT IN TRIPLICATE)

UNITED STATES

DEPARTMENT OF THE INTERIOR
GEOLOGICAL SURVEY

Land Office LA 2 2388

Lease No. 0-24-48

Unit Artesian

SUNDRY NOTICES AND REPORTS ON WELLS

NOTICE OF INTENTION TO DRILL	SUBSEQUENT REPORT OF WATER SHUT-OFF
NOTICE OF INTENTION TO CHANGE PLANS	SUBSEQUENT REPORT OF SHOOTING OR ACIDIZING
NOTICE OF INTENTION TO TEST WATER SHUT-OFF	SUBSEQUENT REPORT OF ALTERING CASING
NOTICE OF INTENTION TO RE-DRILL OR REPAIR WELL	SUBSEQUENT REPORT OF REDRILLING OR REPAIR
NOTICE OF INTENTION TO SHOOT OR ACIDIZE	SUBSEQUENT REPORT OF ABANDONMENT
NOTICE OF INTENTION TO PULL OR ALTER CASING	SUPPLEMENTARY WELL HISTORY
NOTICE OF INTENTION TO ABANDON WELL	

(INDICATE ABOVE BY CHECK MARK NATURE OF REPORT, NOTICE, OR OTHER DATA)

February 20, 19 48

Well No. 1 is located 640 ft. from N line and 640 ft. from E line of sec. 18

18 (Township) 18N (Range) 18E (Meridian)
Los Alamos (County or Subdivision) New Mexico (State or Territory)

The elevation of the derrick floor above sea level is 3221 ft.

DETAILS OF WORK

(State names of and expected depths to objective sands; show sizes, weights, and lengths of proposed casings; indicate mudding jobs, cementing points, and all other important proposed work)

We propose to pull the tubing and rods - and since there was no water in red sand, knock off the 7" casing at approximately 1800' and pull it. We will then run the tubing to bottom and pump mud to the surface; then spot 10 sacks cement 2405 to 2455. 7" casing is cemented with 100 sacks at 2630'. We will then pull the tubing up to where the 7" was knocked off and place another 10 sacks in the stub of pipe, after which we will pull the tubing up to the 2405' and place another 10 sacks there. We will try to get a few joints of 8" and then fill the hole with dirt, erect a pipe marker in cement and close up the location.

Total Depth 2843

I understand that this plan of work must receive approval in writing by the Geological Survey before operations may be commenced.

Company FRANKLIN, ARSON & SONS

Address 5 Miller & Miller

San Jose, Artesia, New Mexico

By Charles R. Hays
Title Assistant Geologist

GEOLOGICAL SURVEY
RECEIVED
FEB 24 1948
Artesia, New Mexico