

APPROVED

AUG 6 1964

RONNIE E. SHOOK
ACTING DISTRICT ENGINEER

(SUBMIT IN TRIPLICATE)

UNITED STATES
DEPARTMENT OF THE INTERIOR
GEOLOGICAL SURVEY

Budget Bureau No. 42-R358.4.
Form Approved.

Land Office Las Cruces

Lease No. LC-028978 b

Unit J

SUNDRY NOTICES AND REPORTS ON WELLS

NOTICE OF INTENTION TO DRILL	SUBSEQUENT REPORT OF WATER SHUT-OFF	
NOTICE OF INTENTION TO CHANGE PLANS	SUBSEQUENT REPORT OF SHOOTING OR ACIDIZING	
NOTICE OF INTENTION TO TEST WATER SHUT-OFF	SUBSEQUENT REPORT OF ALTERING CASING	
NOTICE OF INTENTION TO RE-DRILL OR REPAIR WELL	SUBSEQUENT REPORT OF RE-DRILLING OR REPAIR	
NOTICE OF INTENTION TO SHOOT OR ACIDIZE	SUBSEQUENT REPORT OF ABANDONMENT	X
NOTICE OF INTENTION TO PULL OR ALTER CASING	SUPPLEMENTARY WELL HISTORY	
NOTICE OF INTENTION TO ABANDON WELL		

(INDICATE ABOVE BY CHECK MARK NATURE OF REPORT, NOTICE, OR OTHER DATA)

March 3, 1964, 19

Well No. McClay 3 is located 1980 ft. from N line and 1930 ft. from E line of sec. 33

33 18S 30E NMP
(1/4 Sec. and Sec. No.) (Twp.) (Range) (Meridian)

Benson Queen Eddy New Mexico
(Field) (County or Subdivision) (State or Territory)

The elevation of the derrick floor above sea level is _____ ft.

DETAILS OF WORK

(State names of and expected depths to objective sands; show sizes, weights, and lengths of proposed casings; indicate mudding jobs, cementing points, and all other important proposed work)

10 Sx. plug 3030-3000

10 Sx. plug 2848-2818

20 Sx. plug 1465-1405

20 Sx. plug 600 - 540

Filled in between each with mud. Had oral permission to plug in this way from Mr. Frost

RECEIVED

MARKERS SET

AUG 7 1964

O. C. C.
ARTESIA, OFFICE

I understand that this plan of work must receive approval in writing by the Geological Survey before operations may be commenced.

Company SIMMS & REESE OIL COMPANY

Address 200 Booker Building

Artesia, New Mexico

RECEIVED
MAR 3 1964
U. S. GEOLOGICAL SURVEY
ARTESIA, NEW MEXICO

By Sullivan Symum

Title Partner Bookkeeper