			NEW MEXI	CO OIL CON	SERVA	TION	COMMISSI	ON	•	FORM C-103	
(Rev 3-55)											
(Submit to appropriate District Office as per Commission Rule 1106)											
Name of Company Nalco Refineries, Inc.						Address 1404 Ray, Artesia, New Mexico					
Lease St	ate R D			Well No. Un	it Letter 0	Section 36	Township	18	Range	30	
Date Work Pe 5/25			Pool Culwi	Nunder	La)	· · · · · · · · · · · · · · · · · · ·	County Edd	ly		·······	
THIS IS A REPORT OF: (Check appropriate block)											
Beginning Drilling Operations Image: Casing Test and Cement Job Other (Explain): Image: Plugging Remedial Work											
Detailed account of work done, nature and quantity of materials used, and results obtained.											
Ran 702 feet of 8-5/8", 24#, H-40 new casing, set at 702 feet with 20 sx cement. 5/22/59: Ran 3145 feet of 4-1/2", 9.5#, J-55 new casing set at 3140 feet with 175 sx cement. 5/24/59: Treated formation with 30,000 gallons oil and 118,000 lbs. of 2/40 sand. Witnessed by Position Mitnessed by Position Fill IN BELOW FOR REMEDIAL WORK REPORTS ONLY ORIGINAL WELL DATA											
D F Elev.	3523	TD	3193	PBTD	3131		Producing 3090	Interval - 3108	Cor	npletion Date 5/21/59	
Tubing Diameter 2 BUE			Tubing Depth 3068		Oil String Diam		ter ./2	Oil Strir	ng Dept 31	40	
Perforated In		000		14 10-11-4			#				
3090 - 3108 6/Ft. Bullets Open Hole Interval Producing Formation(s) Queen											
	<u>.</u>		·····	RESULTS	OF WOR	KOVER				· · · · · · · · · · · · · · · · · · ·	
Test	lest		Oil Productio BPD	on Gas Productio MCFPD		Water Production BPD		GOR Cubic feet/Bbl		Gas Well Potential MCFPD	
Before Workover											
After Workover											
						I hereby certify that the information given above is true and complete to the best of my knowledge.					
Approved by Marmiltong					Name	Name a.J. Reans					
Title OIL AND GAS INSPECTOR						Position Dist. Prod. Supt.					
Date JUN 1 1959					Comp	any Ma	lco Rei	fineries	, In	o.	

•

· · · ·

•

· · ·

ARTION COMMISSION

U. S. C. S. Transporter