N. M. O. C.	
GEOLOGICAL SURVEY	LC-029420 (b)
SUNDRY NOTICES AND REPORTS ON WELLS (Do not use this form for proposals to drill or to deepen or plug back to a different reservoir. Use "APPLICATION FOR PERMIT-" for such proposals.)	6. IF INDIAN, ALLOTTEE OR TRIBE NAME
Lie "APPLICATION FOR FRAMIL" - TO SUCH PROPOSAIS./	7. UNIT AGREEMENT NAME
OIL GAS WELL OTHER	Skelly Unit
2. NAME OF OPERATOR	8. FARM OR LEASE NAME
Skelly Oil Company	Skelly Unit
ADDRESS OF OPERATOR	9. WELL NO. 99
P. O. Box 1351, Midland, Texas 79701 LOCATION OF WELL (Report location clearly and in accordance with any State requirements.* See also space 17 below.) At surface	10. FIELD AND POOL, OB WILDCAT San Andres
Unit Letter K, 1980' FSL & 1980' FWL, Sec. 28-17S-31E	11. SEC., T., R., M., OR BLK. AND SURVEY OR AREA
	Sec. 28-175-31E 12. COUNTY OF PARISH 13. STATE
14. PERMIT NO. 15. ELEVATIONS (Show whether DF, RT, GR, etc.) 277/1 DE	
3774' DF	Eddy New Mexico
6. Check Appropriate Box To Indicate Nature of Notice, Report, or	Other Data
NOTICE OF INTENTION TO:	QUENT REPORT OF:
TEST WATER SHUT-OFF PULL OR ALIER CASING WATER SHUT-OFF	REPAIRING WELL
FRACTURE TREAT	ALTERING CASING
SHOOT OR ACIDIZE ABANDON* SHOOTING OR ACIDIZING Fractur	e treatment
REPAIR WELL CHANGE PLANS (Other) I I GOUGE (NOTE : Report result	ts of multiple completion on Well spletion Report and Log form.)
(Other) Completion or Recom 7. DESCRIBE PROPOSED OR COMPLETED OFERATIONS (Clearly state all pertinent details, and give pertinent date proposed work. If well is directionally drilled, give subsurface locations and measured and true vert	es, including estimated date of starting any
<ol> <li>Cleaned out 3758-3780'.</li> <li>Spotted 150 gals. 15% acid 3702-3761'.</li> <li>Treated San Andres open hole 3688-3780' with 1000 gals. 1 gelled brine, 22,000# 20/40 sand.</li> <li>Flow tested open hole 3688-3780' thru 3-1/2" OD frac tubi choke, 12 bbls. oil, 661 bbls. load water, 8060 bbls. for</li> <li>Pulled 3-1/2" OD tubing and set 114 joints (3476') 2-3/8"</li> <li>Flowed San Andres open hole 9 days, 1" choke, 1 bbl. oil,</li> <li>Well is currently shut down for evaluation of further rec attempts.</li> </ol>	ng 9 days, 14/64-24/64" mation water. FTP 105-240 OD 4.7# EUE tubing at 348 7258 bbls. water. FTP 70 onditioning or recompletio
RECEIVED	RECEN
0GT 27 1975	RECEIVED OCT 24 1975 ARTESIA, NEW SUD
C. C. C.	U.S. GEOLOGICAL SURVEY
18. I hereby certify that the foregoing is true and correct (Signed) D. R. Crow, R. Crow TITLE Lead Clerk SIGNED	DATE10-23-75
(This space for Federal or State office use)	
APPROVED BY TITLE	DATE
OCT 24 Line *See Instructions on Reverse Side	
CORRECT CONTRACTOR	

• :