5-USGS-ARTESTA

T-W.D. CHKI_LITDIMIND 1-FILE

Form 9-331 Dec. 1973

1-R. J STARRAK-TULSA N.M.O.C.D. COPY

Form Approved. Budget Bureau No. 42-R1424

UNITED STATES
DEPARTMENT OF THE INTERIOR
GEOLOGICAL SURVEY

UNITED STATES DEPARTMENT OF THE INTERIOR GEOLOGICAL SURVEY	5. LEASE IC-029420 (b) 6. IF INDIAN, ALLOTTEE OR TRIBE NAME
SUNDRY NOTICES AND REPORTS ON WELLS Do not use this form for proposals to drill or to deepen or plug back to a different eservoir. Use Form 9-331-C for such proposals.)	7. UNIT AGREEMENT NAME 8. FARM OR LEASE NAME
1. oil well K well other 2. NAME OF OPERATOR Getty Oil Company 3. ADDRESS OF OPERATOR P. O. Box 730, Hobbs, NM 88240 4. LOCATION OF WELL (REPORT LOCATION CLEARLY. See space 17 below.) AT SURFACE: Unit Letter K 1980' FSL & 1980' FWL AT TOP PROD. INTERVAL: AT TOTAL DEPTH: 16. CHECK APPROPRIATE BOX TO INDICATE NATURE OF NOTICE,	Skelly Unit 9. WELL NO. 99 10. FIELD OR WILDCAT NAME Grayburg Jackson (sf Q J SA) 11. SEC., T., R., M., OR BLK. AND SURVEY OR AREA Sec. 28-175-31E 12. COUNTY OR PARISH Eddy 13. STATE Eddy New Mexico 14. API NO.
REPORT, OR OTHER DATA	15. ELEVATIONS (SHOW DF, KDB, AND WD) 3774' DF
REQUEST FOR APPROVAL TO: SUBSEQUENT REPORT OF: TEST WATER SHUT-OFF	
Riser on <u>8 5/8" OD</u> and <u>5 1/2" OD</u> casing br	rought to surface.
Inspected by B. W. Weaver (NYOCC) on	
Inspected by Mike Williams (NMOCC) on	. O. C. C.
Inspected by James Brasfield (USGS) on Inspected by Bird Jones (USGS) on	MAY 2 1979 .
Subsurface Safety Valve: Manu. and Type	Set @ Ft.
18. Thereby certify that the foregoing is true and correct SIGNED // (/ / / / / / / / / / / / / / Area Sup	MAY 8 1979
Fordard or State	office use) TENGINEER DATE OLG 9 187