

(SUBMIT IN TRIPLICATE)

UNITED STATES  
DEPARTMENT OF THE INTERIOR  
GEOLOGICAL SURVEYLand Office Las Cruces  
Lease No. 029415 (b)  
Unit 7

RECEIVED

## SUNDRY NOTICES AND REPORTS ON WELLS

AUG 8 1960

NOTICE OF INTENTION TO DRILL	SUBSEQUENT REPORT OF WATER SHUT-OFF	
NOTICE OF INTENTION TO CHANGE PLANS	SUBSEQUENT REPORT OF SHOOTING OR ACIDIZING	
NOTICE OF INTENTION TO TEST WATER SHUT-OFF	SUBSEQUENT REPORT OF ALTERING CASING	
NOTICE OF INTENTION TO RE-DRILL OR REPAIR WELL	SUBSEQUENT REPORT OF RE-DRILLING OR REPAIR	
NOTICE OF INTENTION TO SHOOT OR ACIDIZE	SUBSEQUENT REPORT OF ABANDONMENT	<u>of Abo</u> X
NOTICE OF INTENTION TO PULL OR ALTER CASING	SUPPLEMENTARY WELL HISTORY	
NOTICE OF INTENTION TO ABANDON WELL		

(INDICATE ABOVE BY CHECK MARK NATURE OF REPORT, NOTICE, OR OTHER DATA)

August 2, 1960

**Puckett "B"**  
Well No. 19 is located 1980 ft. from [N] line and 1980 ft. from [EX] line of sec. 25  
[W]  
SE 1/4 NW 1/4 Sec. 25 17N 31E 104PM  
(1/4 Sec. and Sec. No.) (Twp.) (Range) (Meridian)  
Maljamar Eddy New Mexico  
(Field) (County or Subdivision) (State or Territory)

The elevation of the derrick floor above sea level is 3946 ft.

## DETAILS OF WORK

(State names of and expected depths to objective sands; show sizes, weights, and lengths of proposed casings; indicate mudding jobs, cementing points, and all other important proposed work)

On July 25, 1960, spotted 20 sacks of cement from 7515 to 7947'. Cut 5 1/2" casing at 3140' and pulled. Loaded hole with mud. Set cast iron bridge plug in 8 5/8" casing at 4010' with cement on top to 4005'.

I understand that this plan of work must receive approval in writing by the Geological Survey before operations may be commenced.

Company William A. & Edward R. HudsonAddress 1910 Electric Bldg.Fort Worth, Texas

By

Title

Consulting Engineer