NM OIL CONS COMMISSION

clsF Drawer DD Artesia, NM 88210

Form 3160-5

UNITED STATES

FORM APPROVED

Julie 1330)	F LAND MANAGEMENT			Budget Bureau No. 1004-0135 Expires: March 31, 1993			
SUNDRY NOTICES AND REPORTS ON WELLS Do not use this form for proposals to drill or to deepen or reentry to a different reservoir.			5. Lease De	5. Lease Designation and Serial No. LC-029418 B			
Use "APPLICATION FOR PERMIT —" for such proposals			6. If Indian,	Alottee or Tribe Na	me		
SUBMIT IN TRIPLICATE			7. If Unit or	7. If Unit or CA, Agreement Designation			
1. Type of Well: OIL GAS	П	8. Well Nam	8. Well Name and Number				
2. Name of Operator				LEA D			
TEXACO EXPLORATION & PRODUCTION INC.				5			
3. Address and Telephone No. P.O. BOX 730, HOBBS, NM 88240 397-0431				9. API Well No. 3001505415			
4. Location of Well (Footage, Sec., T., R., M., or Survey Description) Unit Letter !: 1980 Feet From The SOUTH Line and 660 Feet From The				10. Field and Pool, Exploaratory Area GRAYBURG JACKSON 7RVS-QN-GB-SA			
EAST Line Section 26 Township 17S Range 31E				11. County or Parish, State EDDY , NEW MEXICO			
12. Check Appropriate	Box(s) To Indicate N	lature of Notice	, Report, or 0	Other Data			
TYPE OF SUBMISSION			TYPE OF ACT				
Notice of Intent Subsequent Report Final Abandonment Notice	Abandon Recompl Plugging Casing R Attering OTHER:	letion Back Repair	ABANDON	Change of Pi New Constru Non-Routine Water Shut-C Conversion to Dispose Wate (Note: Report results of macompletion or Recompletion or Recompletion)	ction Fracturing Off Dinjection or ultiple completi	ion on Well	
 Describe Proposed or Completed Operations (Clework. If well is directionally drilled, give subsur TA STATUS IS REQUESTED BECAUSE THE IT TO PRODUCTION. NOTIFY BLM 24 HOURS IN ADVANCE OF 	face locations and measured an	nd true vertical depths t	for all markers, and	zones pertinent to	this work,	i*.	
2. MIRU. TOH WITH PRODUCTION EQUIPM					to t		
3. SET CIBP @ 3436' (50' ABOVE UPPERMO		35 FEET OF CEMEN	т.		6.3 F :	,	
4. TIH WITH TUBING. LOAD HOLE WITH INHIBITOR FLUID. TEST CASING AND PLUG WITH 500 PSI FOR 30 MIN.					* .	1.1	
5. CLASSIFY WELL TO TA STATUS. TEPI WILL SUBMIT PRESSURE CHART AND SUBSEQUENT RE REQUESTING TEMPORARILY ABANDONMENT STATUS ON THIS WELL.			ENT REPORT			(1) (1)	
			O. See See See See See See See See See Se	V	. <u>Ş</u> .		
14. I hereby certify that the foregoing is true and correct SIGNATURE	TITLE Eng	ineering Assistant	<u>t</u>	DATE		6/29/94	
	J. Carriger						
APPROVED BY OPPOVAL, IF ANY:	G. LARA TITLE P	ETROLEUM E	NGINEER ev Joymee	DATE 10	190	chys.	

Title 18 U.S.C. Section 1001, makes it a crime for any person knowingly and willfully to make to any department or agency of the United States any false, fictitious or fraudulent statements of representations as to any matter within its jurisdiction.

BUREAU OF LAND MANAGEMENT CARLSBAD RESOURCE AREA

Temporary Abandonment of Wells on Federal Lands

Conditions of Approval

According to 43 CFR 3162.3-4-c, " No well may be temporarily abandoned for more than 30 days without the prior approval of the authorized officer".

Temporary Abandonment (TA) status approval requires a successful casing integrity test as follows:

- 1. Contact the appropriate BLM office at least 24 hours prior to the scheduled Casing Integrity Test. For wells in Eddy County call (505) 887-6544; for wells in Lea County call (505) 393-3612.
- 2. A bridge plug or packer shall be set at a maximum of 50 feet above any open perforations or open hole.
- 3. All downhole production/injection equipment (tubing, rods, etc.) shall be removed from the casing if they are not isolated by a packer.
- 4. The production casing shall be filled with corrosion inhibited fluid and pressure tested to 500 psi. The casing shall be capable of holding this pressure for at least 30 minutes with a 10% allowable leak-off.

Wells that successfully pass the casing integrity test will be approved for Temporary Abandonment (TA) status for 12 months provided that the operator:

- Submits a subsequent Sundry Notice requesting Th approval,
- 2. Attaches a clear copy or the original of the pressure test chart,
- 3. And attaches a detailed justification why the well should not be plugged and abandoned.

The TA status could be extended without another casing integrity test provided there was no leak-off during the test.

If the well does not pass the casing integrity test, then the operator shall within 30 days submit to BLM for approval one of the following:

- 1. A procedure to repair the casing so that a TA approval can be granted.
- 2. A procedure to plug and abandon the well.