

UNITED STATES  
DEPARTMENT OF THE INTERIOR  
BUREAU OF LAND MANAGEMENT

SUBMIT IN TRIPLICATE \*  
(Other Instructions on  
reverse side)

Budget Bureau No. 1004-0135  
Expires August 31, 1985

CISF

SUNDRY NOTICES AND REPORTS ON WELLS

(Do not use this form for proposals to drill or to deepen or plug back to a different reservoir.  
Use "APPLICATION FOR PERMIT - " for such proposals.)

N.M. Oil Cons. Division  
811 S. 1st Street  
Artesia, NM 88210-2834

|                                                                                                                                                                                             |  |                                                                       |                 |
|---------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------|--|-----------------------------------------------------------------------|-----------------|
| 1. OIL WELL <input checked="" type="checkbox"/> GAS WELL <input type="checkbox"/> OTHER <input type="checkbox"/>                                                                            |  | 5. LEASE DESIGNATION AND SERIAL NO.<br>NM-98121                       |                 |
| 2. NAME OF OPERATOR<br>The Wiser Oil Company                                                                                                                                                |  | 6. IF INDIAN, ALLOTTEE OR TRIBE NAME                                  |                 |
| 3. ADDRESS OF OPERATOR<br>P.O. Box 2568 Hobbs, New Mexico 88241 (505) 392-9797                                                                                                              |  | 7. UNIT AGREEMENT NAME<br>Skelly Unit                                 |                 |
| 4. LOCATION OF WELL (Report location clearly and in accordance with any State requirements.<br>See also space 17 below.)<br>At surface<br>1980' FNL & 1980' FEL Unit G Section 27-T17S-R31E |  | 8. FARM OR LEASE NAME                                                 |                 |
| 14. PERMIT NO                                                                                                                                                                               |  | 9. WELL NO.<br>97 30-015-05 425 354                                   |                 |
| 15. ELEVATIONS (Show whether DF, RT, GR, etc.)<br>3820' GL                                                                                                                                  |  | 10. FIELD AND POOL, OR WILDCAT<br>Grayburg Jackson 7-Rivers-QN-GB-SA  |                 |
|                                                                                                                                                                                             |  | 11. SEC., T., R., M., OR BLK. AND SURVEY OR AREA<br>Sec. 27-T17S-R31E |                 |
|                                                                                                                                                                                             |  | 12. COUNTY OR PARISH<br>Eddy                                          | 13. STATE<br>NM |

16. Check Appropriate Box to indicate Nature of Notice, Report, or Other Data

NOTICE OF INTENTION TO:

|                                              |                                               |
|----------------------------------------------|-----------------------------------------------|
| TEST WATER SHUT-OFF <input type="checkbox"/> | PULL OR ALTER CASING <input type="checkbox"/> |
| FRACTURE TREAT <input type="checkbox"/>      | MULTIPLE COMPLETE <input type="checkbox"/>    |
| SHOOT OR ACIDIZE <input type="checkbox"/>    | ABANDON* <input checked="" type="checkbox"/>  |
| REPAIR WELL <input type="checkbox"/>         | CHANGE PLANS <input type="checkbox"/>         |
| (Other)                                      |                                               |


SUBSEQUENT REPORT OF:

|                                                |                                          |
|------------------------------------------------|------------------------------------------|
| WATER SHUT-OFF <input type="checkbox"/>        | REPAIRING WELL <input type="checkbox"/>  |
| FRACTURE TREATMENT <input type="checkbox"/>    | ALTERING CASING <input type="checkbox"/> |
| SHOOTING OR ACIDIZING <input type="checkbox"/> | ABANDONMENT* <input type="checkbox"/>    |
| (Other)                                        |                                          |

(Note: Report results of multiple completion on Well Completion or Recompletion Report and Log form.)

17. DESCRIBE PROPOSED OR COMPLETED OPERATIONS: (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work. If well is directionally drilled, give subsurface locations and measured and true vertical depths for all markers and zones pertinent to this work.)

1. TIH & set CIBP @ 3350'. Pump 25 sks. cmt. on plug. TAG-
2. Circulate abandonment mud.
3. POH to 1750' and pump 25 sk. plug. TAG-
4. Perforate csg. @ 900' & circulate cmt. Leave cmt. @ surface.
5. Install dry hole marker.



SEE ATTACHED FOR  
CONDITIONS OF APPROVAL

18. I hereby certify that the foregoing is true and correct.

SIGNED L. M. Jones TITLE Superintendent DATE June 9, 1999

(This space for Federal or State office use)

APPROVED BY \_\_\_\_\_ TITLE PETROLEUM ENGINEER DATE JUN 22 1999  
CONDITIONS OF APPROVAL, IF ANY:


\*See Instruction On Reverse Side

RECEIVED

JUN 17 '99

BLM  
ROSWELL, NM

Skelly Unit #97



8 5/8" @ 880' Cmt Circulated  
Perforate

1750'

CIBP

3429' - 3787'

5 1/2" Csg set @ 3812'