	5-USGS-ARTESIA	L-A.B. CARI-MUDAND	
form 9-331	1-R. ¹ . STARRAK-TULSA	1-FILE Form Approved. ○ ○ ○ ♡ ♡ Budget Bureau f	
	JNITED STATES	5. LEASE	
	IENT OF THE INTERIOR	LC-029420 (b)	
GEC	DLOGICAL SURVEY	6. IF INDIAN, ALLOTTEE OR TRIB	E NAME
SUNDRY NOTICES AND REPORTS ON WELLS (Do not use this form for proposals to drill or to deepen or plug back to a different reservoir. Use Form 9-331-C for such proposals.)		S 7. UNIT AGREEMENT NAME	_ _
		fferent	
		Skelly Unit	
1. oil gas well well	other	9. WELL NO.	
2. NAME OF OPERATOR		88	
Getty Oil Comp	any	10. FIELD OR WILDCAT NAME Grayburg Jackson	
3. ADDRESS OF OPERA		11. SEC., T., R., M., OR BLK. AND	SURVEY OR
P. O. BOX 730,	HODDS, NA 88240 REPORT LOCATION CLEARLY. See spa	AREA	
AT SURFACE: Unit	Letter A 660' FNL & 660'	FEL 12. COUNTY OR PARISH 13. ST Eddy New	ATE Mexico
AT TOP PROD. INTE AT TOTAL DEPTH:	RVAL:	14. API NO.	:
	BOX TO INDICATE NATURE OF NO		
REPORT, OR OTHER		15. ELEVATIONS (SHOW DF, KD 3804' DF	B, AND WD)
REQUEST FOR APPROVAL	L TO: SUBSEQUENT REPORT		
TEST WATER SHUT-OFF			
FRACTURE TREAT SHOOT OR ACIDIZE			· .
REPAIR WELL		(NOTE: Report results of multiple con change on Form 9-330.)	npletion or zone
PULL OR ALTER CASING MULTIPLE COMPLETE		CuduRe ou Lotura-220()	•
CHANGE ZONES			•
ABANDON®		<i>i</i>	·.
(other) Casing Cor			
	D OR COMPLETED OPERATIONS (Cleadate of starting any proposed work. If vertical depths for all markers and zones		
		R	ECEIV
Riser on <u>85</u>	<u>/8" OD</u> and <u>7" OD</u> casi	ng prought to surrace.	<u>มม</u> 1 ภ 107
			JUL 1 0 197
Inspected by	B. W. Weaver (NMOCC) on	•···	O. C. C.
Inspected by	Mike Williams (NMOCC) on		ARTESIA, OFFI
Inspected by	James Brasfield (USGS) on	•	
	Bird Jones (USGS) on	And Constant and C	
		Set @	Ft.
Subsurface Safety Valve:	Manu. and Type		
	the foregoing is true and correct		197 9

•

*See Instructions on Reverse Side