ט האמר עזינדאידע

1-FILE

A 12-12 - WHAT THEFTHE

Form 9-331 Dec. 1973

1-R. J. STARRAK-TULSA

Form Approved. Budget Bureau No. 42-R1424

BEDARTMENT OF THE INTERIOR		
DEPARTMENT OF THE INTERIOR	LC-029420 (b)	
GEOLOGICAL SURVEY	6. IF INDIAN, ALLOTTEE OR TRIBE NAME	
SUNDRY NOTICES AND REPORTS ON WELLS	7. UNIT AGREEMENT NAME	
use this form for proposals to drill or to deepen or plug back to a different		
eservoir. Use Form 9–331–C for such proposals.)	8. FARM OR LEASE NAM	E .
1. oil gas other	Skelly Unit 9. WELL NO.	
2. NAME OF OPERATOR	90 90	
Getty Oil Company	10. FIELD OR WILDCAT N	
B. ADDRESS OF OPERATOR	Grayburg Jackson (sk. & 比, sa)	
P. O. Box 730, Hobbs, NM 88240	11. SEC., T., R., M., OR BLK. AND SURVEY OR	
1. LOCATION OF WELL (REPORT LOCATION CLEARLY. See space 17	AREA Sec. 28-17S-31E	
below.) AT SURFACE: Unit Letter # 660' FNL & 1980' FWL		
AT TOP PROD. INTERVAL:	Eddy	New Mexico
AT TOTAL DEPTH:	14. API NO.	2 + -
5. CHECK APPROPRIATE BOX TO INDICATE NATURE OF NOTICE,		
REPORT, OR OTHER DATA	15. ELEVATIONS (SHOW DF, KDB, AND WD) 3789' DF	
EQUEST FOR APPROVAL TO: SUBSEQUENT REPORT OF:		·
EST WATER SHUT-OFF		
RACTURE TREAT	•	
HOOT OR ACIDIZE	(NOTE: Report results of multiple completion or zone	
ULL OR ALTER CASING	change on Form 9-	
NULTIPLE COMPLETE	•	•
HANGE ZONES [] [] BANDON* []		•
other) Casing Connections		•
including estimated date of starting any proposed work. If well is measured and true vertical depths for all markers and zones pertine	directionally drilled, give sub ent to this work.)*	give pertinent dates, surface locations and
including estimated date of starting any proposed work. If well is measured and true vertical depths for all markers and zones pertine	directionally drilled, give sub	give pertinent dates, surface locations and
including estimated date of starting any proposed work. If well is measured and true vertical depths for all markers and zones pertine Riser on 8 5/8" OD and 7" OD casing br	directionally drilled, give sub ent to this work.)*	surface locations and
including estimated date of starting any proposed work. If well is measured and true vertical depths for all markers and zones pertine Riser on 8 5/8" OD and 7" OD casing br Inspected by B. W. Weaver (NMOCC) on	directionally drilled, give sub ent to this work.)*	surface locations and
including estimated date of starting any proposed work. If well is measured and true vertical depths for all markers and zones pertine Riser on 8 5/8" OD and 7" OD casing br	directionally drilled, give sub ent to this work.)*	RECEIV
Riser on 8 5/8" OD and 7" OD casing br Inspected by B. W. Weaver (NNOCC) on	directionally drilled, give sub	RECEIV JUL 1 0 197
Riser on 8 5/8" OD and 7" OD casing by Inspected by B. W. Weaver (NNOCC) on Inspected by Nike Williams (NNOCC) on	directionally drilled, give sub ent to this work.)*	RECEIV JUL 1 0 197
Inspected by B. W. Weaver (NMOCC) on Inspected by James Brasfield (USGS) on Inspected by Bird Jones (USGS) on	directionally drilled, give subent to this work.)* rought to surface.	RECEIV JUL 1 0 197
Riser on 8 5/8" OD and 7" OD casing by Inspected by B. W. Weaver (NMOCC) on Inspected by Nike Williams (NMOCC) on Inspected by James Brasfield (USGS) on Inspected by Bird Jones (USGS) on Subsurface Safety Valve: Manu. and Type	directionally drilled, give subent to this work.)* rought to surface.	RECEIV JUL 1 0 197
including estimated date of starting any proposed work. If well is measured and true vertical depths for all markers and zones pertine Riser on 8 5/8" OD and 7" OD casing br Inspected by B. W. Weaver (NNOCC) on Inspected by Nike Williams (NNOCC) on Inspected by James Brasfield (USGS) on Inspected by Bird Jones (USGS) on Subsurface Safety Valve: Manu. and Type 18. Thereby cértify that the foregoing is true and correct	directionally drilled, give subsent to this work.)* rought to surface. MAY 9 1979	RECEIV JUL 1 0 197
Inspected by B. W. Weaver (NMOCC) on Inspected by James Brasfield (USGS) on Inspected by Bird Jones (USGS) on Subsurface Safety Valve: Manu. and Type	directionally drilled, give subsent to this work.)* rought to surface. MAY 9 1979	RECEIV JUL 1 0 197
including estimated date of starting any proposed work. If well is measured and true vertical depths for all markers and zones pertine Riser on 8 5/8" OD and 7" OD casing br Inspected by B. W. Weaver (NNOCC) on Inspected by Nike Williams (NNOCC) on Inspected by James Brasfield (USGS) on Inspected by Bird Jones (USGS) on Subsurface Safety Valve: Manu. and Type 18. Thereby cértify that the foregoing is true and correct	directionally drilled, give subent to this work.)* cought to surface. May 2 1979 Set DATE MAY	FL. 8 1979