Form 9-331 Dec. 1973

UNITED STATES

DEPARTMENT OF THE INTERIOR	LC-029420 (b)	
GEOLOGICAL SURVEY	6. IF INDIAN, ALLOTTEE OR TRIBE NAME	
GEOLOGICAL SURVEI		
SUNDRY NOTICES AND REPORTS ON WELLS	7. UNIT AGREEMENT NAME	
Do not use this form for proposals to drill or to deepen or plug back to a different reservoir. Use Form 9–331–C for such proposals.)		N. A.A.F.
Do not use this form 9–331–C for such proposals.)	8. FARM OR LEASE	
1. oil G gas G was Water Injection	Skelly Unit 9. WELL NO.	•
well well other water injection	9. WELL NO.	•
2. NAME OF OPERATOR	10. FIELD OR WILDCAT NAME	
Getty Oil Company	Grayburg Jackson (SR.Q. H.SA)	
3. ADDRESS OF OPERATOR	11. SEC., T., R., M.,	OR BLK. AND SURVEY OR
P. O. Box 730, Hobbs, N.1 88240 4. LOCATION OF WELL (REPORT LOCATION CLEARLY. See space 17	AREA	70)]E
		7S-31E
below.) AT SURFACE: Unit Letter J 1980' FSL & 1980' FEL	12. COUNTY OR PA	RISH 13. STATE New Mexico
AT TOP PROD. INTERVAL:	Lacy	INCW TICKERS
AT TOTAL DEPTH:	14. API NO.	• *
16. CHECK APPROPRIATE BOX TO INDICATE NATURE OF NOTICE,	TE FLENATIONS (S	SHOW DF, KDB, AND WD)
REPORT, OR OTHER DATA	3783' DF	SHOW DI, ROB, ARE WEY
REQUEST FOR APPROVAL TO: SUBSEQUENT REPORT OF:		
REQUEST FOR APPROVAL TO: SUBSEQUENT REPORT OF: TEST WATER SHUT-OFF		•
FRACTURE TREAT		
SHOOT OR ACIDIZE	MIGTE: Paport result	s of multiple completion or zone
REPAIR WELL	change on F	orm:9-330.)
PULL OR ALTER CASING		•
MULTIPLE COMPLETE		
ARANDON*		
(other) Casing Connections	ż	1
17. DESCRIBE PROPOSED OR COMPLETED OPERATIONS (Clearly stating including estimated date of starting any proposed work. If well is measured and true vertical depths for all markers and zones pertinent.)	te all pertinent detail directionally drilled, gi ent to this work.)*	s, and give pertinent dates, ve subsurface locations and
·		·
Riser on 8 5/8" OD and 5 1/2" OD casing by	cought to surfa	ce.
Riser on <u>0 37 0 02</u>		RECEIVE
		- 1070
Inspected by B. W. Weaver (NMOCC) on		JUL 1 0 1979
Inspected by B. W. Weaver (Masses)		_
Inspected by Mike Williams (NMOCC) on $_$		O. C. C.
Inspected by James Brasfield (USGS) on		ARTEBIA, OFFICE
Inspected by Bird Jones (USGS) on	MAY 2 1913	•
Inspected by BIId bones (obes, or		
Subsurface Safety Valve: Manu. and Type		Set @ Ft.
18. I hereby certify that the foregoing is true and correct		MAY 8 1979
SIGNED / CONSTRUCT TITLE Area Sur	DT DATE	
D. R. Crockett (This space for Federal or State		
(Orio Sad) TOP O TABLE ACTING DISTR		JUL 9 - 1979

(Orig. Sgd.) JOE G. LARA TITLE ACTING DISTRICT ENGINEER

APPROVED BY CONDITIONS OF APPROVAL, IF ANY.