



(SUBMIT IN TRIPLICATE)

 UNITED STATES
 DEPARTMENT OF THE INTERIOR
 GEOLOGICAL SURVEY

 Land Office Las Cruces
 Lease No. 029395 (b)
 Unit Turner "B" SP

RECEIVED

MAR 30 1961

SUNDRY NOTICES AND REPORTS ON WELLS

NOTICE OF INTENTION TO DRILL.....	SUBSEQUENT REPORT OF WATER SHUT-OFF.....	ARTESIA, <u>OFF</u>
NOTICE OF INTENTION TO CHANGE PLANS.....	SUBSEQUENT REPORT OF SHOOTING OR ACIDIZING.....	
NOTICE OF INTENTION TO TEST WATER SHUT-OFF.....	SUBSEQUENT REPORT OF ALTERING CASING.....	
NOTICE OF INTENTION TO RE-DRILL OR REPAIR WELL.....	SUBSEQUENT REPORT OF RE-DRILLING OR REPAIR.....	
NOTICE OF INTENTION TO SHOOT OR ACIDIZE.....	SUBSEQUENT REPORT OF ABANDONMENT.....	<u>XX</u>
NOTICE OF INTENTION TO PULL OR ALTER CASING.....	SUPPLEMENTARY WELL HISTORY.....	
NOTICE OF INTENTION TO ABANDON WELL.....		

(INDICATE ABOVE BY CHECK MARK NATURE OF REPORT, NOTICE, OR OTHER DATA)

Hobbs, New Mexico Jan. 9, 19 61Well No. 73 is located 130 ft. from N line and 660 ft. from W line of sec. 29
N/A Sec. 29 17S 11E NMPM
 (1/4 Sec. and Sec. No.) (Twp.) (Range) (Meridian)

Undesignated Hddy New Mexico
 (Field) (County or Subdivision) (State or Territory)

The elevation of the derrick floor above sea level is _____ ft.

Verbal approval from Jim Knauf to
C.C. Oethard 1/7/61

DETAILS OF WORK

(State names of and expected depths to objective sands; show sizes, weights, and lengths of proposed casings; indicate mudding jobs, cementing points, and all other important proposed work)

TD 9900' - Dry - Set 2 5/8" CD Casing @ 1600' Cement Circulated

DST# 1 - 7160 to 7190' - Abs - 2 Hrs. Recovered 3994' Black Sulphur Water

IFF 1320- FFF 2300- 2Hr. SIP 2694'

DST# 2 - 9730 to 9779' - Penn.-2 Hrs. Recovered 20' Drilg. Mud- no show oil, gas or water

IFF & FFF Zero- 2Hr. SIP 904'

Fill hole with heavy mud and set;

40 Sk. Cement Plug 2/ 8346 to 8446'

40 " " " 2/ 7188 to 7285'

40 " " " 2/ 4525 to 4625'

80 " " " 2/ 2940 to 3140'

40 " " " 2/ 2140 to 2240'

40 " " " 2/ 1525 to 1625'

Set 4" "Regulation "Marker" 4' Above surface level in 15Sk. Cement in top 2 5/8" CD Csg. & Bottom of Collar- Fill Collar & Level Location. P&H Completed

I understand that this plan of work must receive approval in writing by the Geological Survey before operations may be commenced.

Company Sinclair Oil & Gas CompanyAddress 520 E. Broadway, Hobbs, N.M.By [Signature]Title Dist. Supt.

RECEIVED

JAN 16 1961

U. S. GEOLOGICAL SURVEY
ARTESIA, NEW MEXICO