

Land Office Las Cruces
Lease No. 029995 (b)
Unit Turner "D" SPUNITED STATES
DEPARTMENT OF THE INTERIOR
GEOLOGICAL SURVEY

SUNDRY NOTICES AND REPORTS ON WELLS

NOTICE OF INTENTION TO DRILL		SUBSEQUENT REPORT OF WATER SHUT-OFF	
NOTICE OF INTENTION TO CHANGE PLANS		SUBSEQUENT REPORT OF SHOOTING OR ACIDIZING	
NOTICE OF INTENTION TO TEST WATER SHUT-OFF	<input checked="" type="checkbox"/>	SUBSEQUENT REPORT OF ALTERING CASING	
NOTICE OF INTENTION TO RE-DRILL OR REPAIR WELL		SUBSEQUENT REPORT OF RE-DRILLING OR REPAIR	
NOTICE OF INTENTION TO SHOOT OR ACIDIZE		SUBSEQUENT REPORT OF ABANDONMENT	<input checked="" type="checkbox"/>
NOTICE OF INTENTION TO PULL OR ALTER CASING		SUPPLEMENTARY WELL HISTORY	
NOTICE OF INTENTION TO ABANDON WELL			

(INDICATE ABOVE BY CHECK MARK NATURE OF REPORT, NOTICE, OR OTHER DATA)

Hobbs, New Mexico January 28, 19 61

Well No. 76 is located 660 ft. from S line and 660 ft. from E line of sec. 30
34 1/4 Sec. 30 173 112 N10W
 (1/4 Sec. and Sec. No.) (Twp.) (Range) (Meridian)
Grayburg-Jackson Hddy New Mexico
 (Field) (County or Subdivision) (State or Territory)

The elevation of the derrick floor above sea level is _____ ft.

DETAILS OF WORK

(State names of and expected depths to objective sands; show sizes, weights, and lengths of proposed casings; indicate mudding jobs, cementing points, and all other important proposed work)

TD 3997 - Dry - no show oil or gas. Spudded 12/20/60- Kincaid & Watson Contractor
Set 8 5/8" OD Casing @ 542' w/ 100 Sha. Cement 12/23/60- Drilled Cement,
Bailed dry- set 1 hour- Tested dry.
Filled hole with heavy mud and set
35 Sack Cement plug f/ 3470 to 3570 (San Andres)
35 " " " f/ 3080 to 3120 (Grayburg)
20 " " " f/ 2644 to 2694 (unknown)
20 " " " f/ 1650 to 1700 (Yates)
20 " " " f/ 1455 to 1503 (Base Salt)
20 " " " f/ 517 to 567 (Base of Surface Casing) (Top Salt 512')
10 " " In bottom of cellar & Top of 8 5/8" OD Casing w/ 4" Regulation Marker
bottoming 4' above surface level- & Level Location MA Completed
(Well Description on Marker)

I understand that this plan of work must receive approval in writing by the Geological Survey before operations may be commenced.

Company Sinclair Oil & Gas CompanyAddress Hobbs, New MexicoBy Lucas
Title Dist. Supt.